

1218134

0635318

105-N & 109-N SAFE STORAGE ENCLOSURE (SSE) FINAL  
ROOM STATUS REPORT

SECTION 10 OF 11

PHOTO # 453/105N/Area Under Main SSE Roof-Vent Valve Cover Plates West End/EI. Varies/09-08-2011



PHOTO # 454/105N/Area Under Main SSE Roof-NW Corner Looking N./El.60'-6"/09-08-2011



PHOTO # 455/105N/Area Under Main SSE Roof-NW Corner Looking East/EI.60'-6"/09-08-2011



PHOTO # 456/105N/Area Under Main SSE Roof-North Side Center/EI.Varies/09-08-2011



PHOTO # 457/105N/Area Under Main SSE Roof-N. Side Center/El.Varies/09-08-2011



PHOTO # 458/105N/Area Under Main SSE Roof-N.Side Above Front Face/EI.60'-6"/09-08-2011



PHOTO # 459/105N/Area Under Main SSE Roof-N.Side Above Frt.Face/EI.60'-6"/09-08-2011



PHOTO # 460/105N/Area Under Main SSE Roof-N.Side at Front Face/EI.60'-6"/09-08-2011



PHOTO # 461/105N/Area Under Main SSE Roof-N.Side Front Face/EI.0'-6"/09-08-2011



PHOTO # 462/105N/Area Under Main SSE Roof-N. Side Looking E./El.Varies/09-08-2011



PHOTO # 463/105N/Area Under Main SSE Roof-Vent Valve Cover Plate E.End/EI.Varies/09-08-2011



PHOTO # 464/105N/Area Under Main SSE Roof-East Side Center/El.Varies/09-08-2011



PHOTO # 465/105N/Area Under Main SSE Roof-Cover Pl. Top Stair#6A/EI.Varies/09-08-2011



PHOTO # 466/105N/Area Under Main SSE Roof-E.Side Looking S./El.Varies/09-08-2011



PHOTO # 467/105N/Area Under Main SSE Roof-Center Looking East/EI.Varies/09-08-2011



PHOTO # 468/105N/Area Under Main SSE Roof-S. Side Looking E./El. Varies/09-08-2011



PHOTO # 469/105N/Area Under Main SSE Roof-S. Side Looking E./El. Varies/09-08-2011



PHOTO # 470/105N/Main SSE Roof-Looking South at Pressurizer/EI. Varies/10-13-2011



PHOTO # 471/105N/Main SSE Roof-Flashing at Pressurizer NW Comer/EI.Varies/10-13-2011



PHOTO # 472/105N/Main SSE Roof-Flashing at Ridge & Concret/EI.Varies/10-13-2011



PHOTO # 473/105N/Main SSE Roof-Looking North/EI.Varies/10-13-2011



PHOTO # 474/105N/Main SSE Roof-Looking West/EI.Varies/10-13-2011



PHOTO # 475/105N/Main SSE Roof-Looking East/El.Varies/10-13-2011



PHOTO # 476/105N/Main SSE Roof-Gutter at West Side/EI.Varies/10-12-2011



PHOTO # 477/105N/Main SSE Roof-Gutter Downspout & Support/El.Varies/10-12-2011




PHOTO # 478/105N/Area Under Rod Rm. SSE Roof-Looking SW/EI.40'/08-01-2011



PHOTO # 479/105N/Area Under Rod Rm. SSE Roof-N. End Looking W./El.+40'/08-01-2011



PHOTO # 480/105N/Area Under Rod Rm. SSE Roof-Cover Plate at Zone I Duct/EI.+40'/08-01-2011



PHOTO # 481/105N/Area Under Rod Rm. SSE Roof-Low Eave Looking West/EI.+40'/08-01-2011



PHOTO # 482/105N/Area Under Rod Rm. SSE Roof-Looking SW/EI.+40'/08-01-2011



PHOTO # 483/105N/Area Under Rod Rm. SSE Roof-South End/EI.+40'/08-01-2011



PHOTO # 484/105N/Area Under Rod Rm. SSE Roof-Cover Plate NW Corner/EI.+40'/08-01-2011



PHOTO # 485/105N/Area Under Rod Rm. SSE Roof-N. Wall Siding/EI.+40'/08-01-2011



PHOTO # 486/105N/Area Under Rod Rm. SSE Roof-Floor Plate at NE Corner/EI.+40'/08-01-2011



PHOTO # 487/105N/Area Under Rod Rm. SSE Roof-Looking East/EI.+40'/08-01-2011




PHOTO # 488/105N/Area Under Rod Rm. SSE Roof-Cover Plate at East Wall/EI.+40'/08-01-2011



PHOTO # 489/105N/Area Under Rod Rm. SSE Roof-Door at SE Corner/EI.40'/08-01-2011



PHOTO # 490/105N/Area Under Rod Rm. SSE Roof-S.End Looking W./El.+40'/08-01-2011



PHOTO # 491/105N/Area Under Rod Rm. SSE Roof-South Wall Siding/EI. +40'/08-01-2011



PHOTO # 492/105N/Rod Rm. SSE Roof-North Wall Siding/EI.Varies/08-02-2011




PHOTO # 493/105N/Rod Rm. SSE Roof-Flashing at Concrete Wall/EI. Varies/08-02-2011



PHOTO # 494/105N/Rod Rm. SSE Roof-Flashing at Concrete Wall/EI.Varies/08-02-2011



PHOTO # 495/105N/Rod Rm. SSE Roof-Flashing Splice/EI.Varies/08-02-201



PHOTO # 496/105N/Rod Rm. SSE Roof-South Wall Siding/EI.Varies/08-02-2011



PHOTO # 497/105N/Rod Rm. SSE Roof-Looking North/EI.Varies/08-02-2011



PHOTO # 498/105N/Rod Rm. SSE Roof-Flashing at Concrete Wall/EI.Varies/08-02-2011



PHOTO # 499/105N/Rod Rm. SSE Roof-North Wall Siding/EI.Varies/08-18-2011



PHOTO # 500/105N/Rod Rm. SSE Roof-Framing at NE Corner/EI.+40'/08-18-2011




PHOTO # 501/105N/Rod Rm. SSE Roof-Framing at NE Corner/EI.+40'/08-18-2011




PHOTO # 502/105N/Rod Rm. SSE Roof-West Wall Siding/EI.Varies/08-18-2011



PHOTO # 503/105N/Rod Rm. SSE Roof-West Wall Siding/EI.Varies/08-18-2011

