



## Department of Energy

Richland Operations Office  
P.O. Box 550  
Richland, Washington 99352

9300857

SEP 24 1992

92-WOB-401

Mr. David B. Jansen, P. E.  
Hanford Project Manager  
State of Washington  
Department of Ecology  
P. O. Box 47600  
Olympia, Washington 98504-7600

REQUEST FOR VARIANCE RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) WELLS  
299-W6-4, 199-N-71, AND 699-E43-40

This addendum provides clarification and corrects a casing diameter error in the original reference request to the State of Washington Department of Ecology. The error was discovered in the section entitled "RCRA Well 699-43-40 (216-B-Pond System)" and should read as follows:

This well does not comply with the WAC 173-160-520 because a 12-inch long portion of the temporary casing shoe inadvertently detached from the temporary 10-inch diameter casing during pull back operations. The shoe is located adjacent to the stainless steel screen interval (see Well Summary Report in Appendix B.) The well had been backfilled with bentonite and all of the 10-inch diameter casing removed before it was realized that the shoe had detached from the casing. The well was completed on October 24, 1991, and Ms. Kowalik was informed of the problem on November 4, 1991.

If you have any questions concerning this addendum or the request for variance please contact Mr. M. J Furman of my staff on (509) 376-7062.

Sincerely,

June M. Hennig, Director  
Waste Management Division

cc: K. R. Fecht, WHC  
R. E. Lerch, WHC  
K. K. Kowalik, Ecology



