# 1218134

0635318

105-N & 109-N SAFE STORAGE ENCLOSURE (SSE) FINAL ROOM STATUS REPORT

SECTION 9 OF 11



PHOTO # 402/105N/Rm.#520-North End Looking North/EI.+51'/02-07-2012


## PHOTO # 403/105N/Rm.#520-South End Looking South/EI.+51'/02-07-2012





## PHOTO # 404/105N/Rm.#610-Looking North/EI.60'-6"/02-07-2012





## PHOTO # 407/105N/Rm.#602-Looking East/El.+60'-6"/02-07-2012





PHOTO # 408/105N/Rm.#602-Looking West/El.+60'-6"/02-07-2012



PHOTO # 409/105N/Rm.#603-Looking East Toward Rm.#602/EI.+60'-6"/02-07-2012

PHOTO # 410/105N/Rm.#603-Looking East Toward Rm.#613/EI.+60'-6"/02-07-2012




## PHOTO # 411/105N/Rm.#603-Looking West/El.60'-6"/02-07-2012





PHOTO # 412/105N/Rm.#603-Looking South at Door to 109N Pressurizer/EI.+60'-6"/02-07-2012

#### PHOTO # 413/105N/Rm.#606-East Side Looking North/EI.+60'-6"/02-07-2012



#### PHOTO # 414/105N/Rm.#606-NW Corner/El.+60'-6"/02-07-2012





## PHOTO # 415/105N/Rm.#606 Cover Plate at Door Opening-NW Corner/El.+60'-6"/02-07-2012

## PHOTO # 416/105N/Rm.#606-West Side Looking South/El.+60'-6"/02-07-2012





PHOTO # 417/105N/Rm.#611-Looking West/El.+60'-6"/02-07-2012



PHOTO # 418/105N/Rm.#612 Doorway from Rm.#607-Looking East/El.+60'-6"/02-07-2012



PHOTO # 419/105N/Rm.#607 Passive HEPA Filter-South Side Looking West/El.+60'-6"/02-07-2012




PHOTO # 420/105N/Rm.#607 Passive HEPA Filter in Wall of Zone I Duct-South Wall/El.+60'-6"/02-07-2012



PHOTO # 421/105N/Rm.#607-Shld.Door at E. Wall of Rm.#608/EI.+60'-6"/02-07-2012

PHOTO # 422/105N/Rm.#607-NE Corner/El.+60'-6"/02-07-2012






PHOTO # 423/105N/Rm.#607-Center Looking West/El.+60'-6"/02-07-2012



PHOTO # 424/105N/Rm.#607-West Side Looking West/EI.+60'-6"/02-07-2012







PHOTO # 426/105N/Rm.#609 NW Corner-Looking East/El.+60'-6"/02-07-2012









## PHOTO # 429/105N/Stair#6 Level Switches-Bottom of Stair/El.(-)24'/02-15-2012







PHOTO # 431/105N/Stair#6 +5' Landing-Looking from Above/EI.+5'/02-15-2012




PHOTO # 432/105N/Stair#6 +40' Landing-Looking Down/El.+40'/02-15-2012



PHOTO # 433/105N/Stair#6A +60' Landing-Looking Up at Temp.Switches/EI.+60'-6"/02-15-2012

## PHOTO # 434/105N/Stair#6A Temperature Switches-Top of Stair/El.+60'-6"/02-15-2012



#### PHOTO # 435/105N/Stair#6A +60' Landing-Looking Down to +40'/ El.+60'-6"/02-15-2012



## PHOTO # 436/105N/Area Under Main SSE Roof-Looking West at SW Corner/El.Varies/09-08-2011









PHOTO # 438/105N/Area Under Main SSE Roof-NW Corner Pressurizer Connection/El.Varies/09-08-2011







## PHOTO # 441/105N/Area Under Main SSE Roof-Looking East/El.Varies/09-08-2011



## PHOTO # 443/105N/Area Under Main SSE Roof-Center Looking West/El.Varies/09-08-2011













PHOTO # 446/105N/Area Under Main SSE Roof-Hatch Cover/El.Varies/09-08-2011




PHOTO # 447/105N/Area Under Main SSE Roof-Center Looking West/Ev.Varies/09-08-2011



PHOTO # 448/105N/Area Under Main SSE Roof-NW Corner/El.Varies/09-08-2011



## PHOTO # 449/105N/Area Under Main SSE Roof-Cover Plate at Penetration/El.Varies/09-08-2011



## PHOTO # 450/105N/Area Under Main SSE Roof-West SideCenter/EI.Varies/09-08-2011





