START

332 Storage Facility 5/19/88 Rev. 0 000193

Please Print or Type in the Unshaded Areas Only
(Fill-in areas are spaced for elite type, i.e., 12 characters/inch).

FORM 3

DANGEROUS WASTE PERMIT APPLICATION

I. EPA/STATE I.D. NUMBER: W A 7 8 9 0 0 0 8 9 6 7

FOR OFFICIAL USE ONLY

APPLICATION APPROVED	DATE RECEIVED (mo., day, & yr.)	COMMENTS

II. FIRST OR REVISED APPLICATION

Place an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your facility or a revised application. If this is your first application and you already know your facility's EPA/STATE I.D. Number, or if this is a revised application, enter your facility's EPA/STATE I.D. Number in Section I above.

A. FIRST APPLICATION *(place an "X" below and provide the appropriate date)*

☐ 1. EXISTING FACILITY *(See instructions for definition of "existing" facility. Complete item below.)*

MO.	DAY	YR.
0 3	0 1	8 4

FOR EXISTING FACILITIES, PROVIDE THE DATE *(mo., day, & yr.)* OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED *(use the boxes to the left)*

☐ 2. NEW FACILITY *(Complete item below.)*

MO.	DAY	YR.

FOR NEW FACILITIES, PROVIDE THE DATE *(mo., day, & yr.)* OPERATION BEGAN OR IS EXPECTED TO BEGIN

B. REVISED APPLICATION *(place an "X" below and complete Section I above)*

☒ 1. FACILITY HAS AN INTERIM STATUS PERMIT

☐ 2. FACILITY HAS A FINAL PERMIT

III. PROCESSES — CODES AND DESIGN CAPACITIES

A. PROCESS CODE — Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process *(including its design capacity)* in the space provided on the *(Section III-C)*.

B. PROCESS DESIGN CAPACITY — For each code entered in column A enter the capacity of the process.
1. AMOUNT — Enter the amount.
2. UNIT OF MEASURE — For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit of measure used. Only the units of measure that are listed below should be used.

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
Storage:		
CONTAINER (barrel, drum, etc.)	S01	GALLONS OR LITERS
TANK	S02	GALLONS OR LITERS
WASTE PILE	S03	CUBIC YARDS OR CUBIC METERS
SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS
Disposal:		
INJECTION WELL	D80	GALLONS OR LITERS
LANDFILL	D81	ACRE-FEET *(the volume that would cover one acre to a depth of one foot)* OR HECTARE-METER
LAND APPLICATION	D82	*ACRES OR HECTARES*
OCEAN DISPOSAL	D83	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	D84	GALLONS OR LITERS

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
Treatment:		
TANK	T01	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY
INCINERATOR	T03	TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR LITERS PER HOUR
OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided; Section III-C.)	T04	GALLONS PER DAY OR LITERS PER DAY

UNIT OF MEASURE	UNIT OF MEASURE CODE
GALLONS	G
LITERS	L
CUBIC YARDS	Y
CUBIC METERS	C
GALLONS PER DAY	U
LITERS PER DAY	V
TONS PER HOUR	D
METRIC TONS PER HOUR	W
GALLONS PER HOUR	E
LITERS PER HOUR	H
ACRE-FEET	A
HECTARE-METER	F
ACRES	B
HECTARES	Q

EXAMPLE FOR COMPLETING SECTION III *(shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400* gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.

LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY 1. AMOUNT (specify)	B. PROCESS DESIGN CAPACITY 2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY	LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY 1. AMOUNT (specify)	B. PROCESS DESIGN CAPACITY 2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY
X-1	S 0 2	600	G		5				
X-2	T 0 3	20	E		6				
1	S 0 1	1,800	G		7				
2					8				
3					9				
4					10				

CONTINUE ON REVERSE

Continued from the front.

III. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (code "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

S01

The 332 Storage Facility stores small quantities of radioactive mixed waste (RMW) and dangerous waste and waste samples in the 300 Area in various sized containers from 1 to 85 gallons. The facility was designed to store small quantities of flammables and meets all appropriate codes, including WAC 173-303 spill prevention and control. Storage design capacity is less than 1,800 gallons.

IV. DESCRIPTION OF DANGEROUS WASTES

A. DANGEROUS WASTE NUMBER — Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describes the characteristics and/or the toxic contaminants of those dangerous wastes.

B. ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste(s) that will be handled which possess that characteristic or contaminant.

C. UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non—listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non—listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER — Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

1. Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV *(shown in line numbers X-1, X-2, X-3, and X-4 below)* — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K 0 5 4	900	P	T 0 3 D 8 0	
X-2	D 0 0 2	400	P	T 0 3 D 8 0	
X-3	D 0 0 1	100	P	T 0 3 D 8 0	
X-4	D 0 0 2			T 0 3 D 8 0	included with above

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): WA789008967

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	D001	2,000	K	S01	Storage
2	D002	2,000			
3	D004	200			
4	D005	200			
5	D006	200			
6	D007	200			
7	D008	200			
8	D009	400			
9	D010	50			
10	D011	200			
11	WT01	1,000			
12	WT02	1,000			
13	WP01	1,000			
14	WP02	1,000			
15	WC01	1,000			
16	WC02	1,000			
17	F001	1,000			
18	F002	1,000			
19	F003	1,500			
20	F004	600			
21	F005	1,000			
22	D003	200			
23	WP03	200			
24	F027	50			
25	W001	1,000			
26	P002	50			

CONTINUE ON REVERSE

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	P003	100	K	S01	Storage
2	P004	25			
3	P005	200			
4	P006	25			
5	P008	50			
6	P009	25			
7	P010	50			
8	P011	100			
9	P012	100			
10	P013	25			
11	P014	25			
12	P015	50			
13	P016	100			
14	P017	100			
15	P018	25			
16	P020	25			
17	P021	25			
18	P022	100			
19	P023	25			
20	P024	25			
21	P025	25			
22	P026	25			
23	P027	50			
24	P028	50			
25	P029	25			
26	P030	100			

CONTINUE ON REVERSE

Continued from page 2.

NOTE: *Photocopy this page before completing if you have more than 26 wastes to list.*

I.D. NUMBER (*enter from page 1*): A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (*continued*)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	P031	25	K	S01	Storage
2	P033	25			
3	P034	25			
4	P036	25			
5	P037	50			
6	P038	25			
7	P039	25			
8	P041	25			
9	P042	25			
10	P047	25			
11	P048	100			
12	P049	50			
13	P050	25			
14	P051	25			
15	P054	25			
16	P056	25			
17	P057	25			
18	P058	25			
19	P059	25			
20	P060	25			
21	P062	25			
22	P063	100			
23	P064	25			
24	P065	25			
25	P066	25			
26	P067	25			

CONTINUE ON REVERSE

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (*enter from page 1*): A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (*continued*)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	P068	50	K	S01	Storage
2	P069	25			
3	P070	25			
4	P071	25			
5	P073	25			
6	P074	25			
7	P075	25			
8	P076	25			
9	P077	50			
10	P078	50			
11	P082	25			
12	P087	25			
13	P089	25			
14	P092	25			
15	P093	25			
16	P094	25			
17	P095	50			
18	P096	50			
19	P098	50			
20	P099	25			
21	P101	25			
22	P102	100			
23	P104	25			
24	P105	100			
25	P106	50			
26	P107	25			

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	P108	25	K	S01	Storage
2	P110	25			
3	P113	25			
4	P114	25			
5	P115	50			
6	P119	25			
7	P120	25			
8	P121	25			
9	P122	25			
10	P123	25			
11	U001	200			
12	U002	200			
13	U003	200			
14	U004	100			
15	U005	25			
16	U006	200			
17	U007	200			
18	U008	200			
19	U009	200			
20	U011	25			
21	U012	200			
22	U017	25			
23	U018	25			
24	U019	200			
25	U020	25			
26	U021	100			

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	U 0 2 2	25	K	S 0 1	Storage
2	U 0 2 3	25			
3	U 0 2 5	25			
4	U 0 2 7	25			
5	U 0 2 8	25			
6	U 0 2 9	100			
7	U 0 3 0	25			
8	U 0 3 1	200			
9	U 0 3 2	25			
10	U 0 3 4	100			
11	U 0 3 5	25			
12	U 0 3 6	50			
13	U 0 3 7	200			
14	U 0 3 9	25			
15	U 0 4 1	25			
16	U 0 4 2	25			
17	U 0 4 3	50			
18	U 0 4 4	200			
19	U 0 4 5	50			
20	U 0 4 6	25			
21	U 0 4 7	25			
22	U 0 4 8	100			
23	U 0 4 9	25			
24	U 0 5 0	25			
25	U 0 5 1	50			
26	U 0 5 2	50			

Continued from page 2.
NOTE: *Photocopy this page before completing if you have more than 26 wastes to list.*

I.D. NUMBER (*enter from page 1*): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (*continued*)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U053	25	K	S01	Storage
2	U055	25			
3	U056	100			
4	U057	50			
5	U058	25			
6	U059	25			
7	U060	25			
8	U061	25			
9	U063	25			
10	U064	25			
11	U066	25			
12	U067	50			
13	U068	25			
14	U069	25			
15	U070	100			
16	U071	100			
17	U072	100			
18	U073	25			
19	U074	25			
20	U075	200			
21	U076	50			
22	U077	50			
23	U078	200			
24	U079	200			
25	U080	200			
26	U081	200			

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1)
W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U082	200	K	S01	Storage
2	U083	100			
3	U084	50			
4	U085	25			
5	U086	25			
6	U087	25			
7	U088	25			
8	U089	25			
9	U090	25			
10	U091	25			
11	U092	50			
12	U093	25			
13	U094	25			
14	U095	25			
15	U096	25			
16	U098	25			
17	U099	25			
18	U101	50			
19	U102	25			
20	U103	50			
21	U105	50			
22	U106	50			
23	U107	25			
24	U108	200			
25	U109	50			
26	U110	25			

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U 1 1 1	25	K	S 0 1	Storage
2	U 1 1 2	200			
3	U 1 1 3	50			
4	U 1 1 5	50			
5	U 1 1 6	50			
6	U 1 1 7	50			
7	U 1 1 8	25			
8	U 1 1 9	25			
9	U 1 2 0	25			
10	U 1 2 1	50			
11	U 1 2 2	400			
12	U 1 2 3	200			
13	U 1 2 4	200			
14	U 1 2 5	50			
15	U 1 2 6	50			
16	U 1 2 7	100			
17	U 1 2 8	25			
18	U 1 2 9	25			
19	U 1 3 0	25			
20	U 1 3 1	50			
21	U 1 3 2	25			
22	U 1 3 3	50			
23	U 1 3 4	400			
24	U 1 3 5	200			
25	U 1 3 6	100			
26	U 1 3 8	100			

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U 1 3 9	25	K	S 0 1	Storage
2	U 1 4 0	400			
3	U 1 4 1	25			
4	U 1 4 2	25			
5	U 1 4 4	25			
6	U 1 4 5	100			
7	U 1 4 6	25			
8	U 1 4 7	50			
9	U 1 4 9	25			
10	U 1 5 1	500			
11	U 1 5 2	25			
12	U 1 5 4	400			
13	U 1 5 5	25			
14	U 1 5 8	25			
15	U 1 5 9	400			
16	U 1 6 0	25			
17	U 1 6 1	200			
18	U 1 6 2	200			
19	U 1 6 3	25			
20	U 1 6 5	50			
21	U 1 6 7	25			
22	U 1 6 8	25			
23	U 1 6 9	50			
24	U 1 7 0	50			
25	U 1 7 1	50			
26	U 1 7 3	25			

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (*enter from page 1*): WA 7890008967

IV. DESCRIPTION OF DANGEROUS WASTES (*continued*)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	U174	25	K	S01	Storage
2	U176	25			
3	U177	25			
4	U178	25			
5	U179	25			
6	U181	25			
7	U182	25			
8	U183	50			
9	U184	50			
10	U185	50			
11	U186	50			
12	U188	100			
13	U189	25			
14	U190	25			
15	U191	25			
16	U193	25			
17	U194	25			
18	U196	50			
19	U197	25			
20	U201	50			
21	U202	25			
22	U203	25			
23	U204	25			
24	U205	25			
25	U207	50			
26	U208	100			

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D. NUMBER (enter from page 1): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

LINE NO.	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	U 2 0 9	100	K	S 0 1	Storage
2	U 2 1 0	100			
3	U 2 1 1	400			
4	U 2 1 2	50			
5	U 2 1 3	400			
6	U 2 1 5	25			
7	U 2 1 6	25			
8	U 2 1 7	50			
9	U 2 1 9	25			
10	U 2 2 0	200			
11	U 2 2 2	25			
12	U 2 2 3	25			
13	U 2 2 5	100			
14	U 2 2 6	400			
15	U 2 2 7	100			
16	U 2 2 8	400			
17	U 2 3 0	50			
18	U 2 3 1	50			
19	U 2 3 3	25			
20	U 2 3 4	25			
21	U 2 3 6	25			
22	U 2 3 7	25			
23	U 2 3 8	25			
24	U 2 3 9	200			
25	U 2 4 0	25			
26	U 2 4 2	50			

CONTINUE ON REVERSE

Continued from page 2.

NOTE: *Photocopy this page before completing if you have more than 26 wastes to list.*

I.D. NUMBER (*enter from page 1*): W A 7 8 9 0 0 0 8 9 6 7

IV. DESCRIPTION OF DANGEROUS WASTES (*continued*)

LINE	A. DANGEROUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U243	25	K	S01	Storage
2	U244	50			
3	U246	50			
4	U247	25			
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

Continued from the front.

IV. DESCRIPTION OF DANGEROUS WASTES *(continued)*

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM SECTION D(1) ON PAGE 3.

The dangerous wastes to be stored at the 332 Storage Facility consist of listed wastes, wastes from nonspecific sources, characteristic wastes and state-only (special) wastes.

V. FACILITY DRAWING

All existing facilities must include in the space provided on page 5 a scale drawing of the facility *(see instructions for more detail).*

VI. PHOTOGRAPHS

All existing facilities must include photographs *(aerial or ground—level)* that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites of future storage, treatment or disposal areas *(see instructions for more detail).*

VII. FACILITY GEOGRAPHIC LOCATION *This information appears on the attached drawing and photograph.

LATITUDE *(degrees, minutes, & seconds)*	LONGITUDE *(degrees, minutes, & seconds)*

VIII. FACILITY OWNER

[X] A. If the facility owner is also the facility operator as listed in Section VII on Form 1, "General Information", place an "X" in the box to the left and skip to Section IX below.

B. If the facility owner is not the facility operator as listed in Section VII on Form 1, complete the following items:

1. NAME OF FACILITY'S LEGAL OWNER	2. PHONE NO. *(area code & no.)*

3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST.	6. ZIP CODE

IX. OWNER CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

NAME *(print or type)*	SIGNATURE	DATE SIGNED
Michael J. Lawrence, Manager U.S. DOE, Richland Operations	Michael J. Lawrence	5-19-88

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

NAME *(print or type)*	SIGNATURE	DATE SIGNED

SEE ATTACHMENT

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Michael J. Lawrence, Manager
Department of Energy
Richland Operations Office

5-19-88
Date

William R. Wiley, Director
Pacific Northwest Laboratory

5/19/88
Date

332 Storage Facility

Longitude 119°16'27"
Latitude 46°22'22"

8306228-62CN
Photo Taken 1983

332 Storage Facility
Site Plan



WA7890008967

332 Storage Facility
Building Plan



78604-120.15

WA7890008967