

START

CONVERSATION RECORD

TIME 7:00 pm

DATE 2-19-93

TYPE			ROUTING	
			NAME/SYMBOL	INT
<input type="checkbox"/> VISIT <input type="checkbox"/> CONFERENCE <input checked="" type="checkbox"/> TELEPHONE				
Location of Visit/Conference:				
NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU John Cline			ORGANIZATION (Office, dept., bureau, etc.) Self	TELEPHONE NO. (509)786-1649
SUBJECT Radioactive and Chemical Wastes				

9 5 1 2 9 3 5 1 2 6 5
SUMMARY John worked at site 1100-IU-1 starting in 1947. Related experience working with radioactive substances strontium and plutonium in experiments with foxes at Fox farm at ALE headquarters site. Said all dirt and fenceposts were removed when project was completed. Said all wastes were stored in jugs and sent to burial sites which were not located at ALE but at Hanford somewhere. Didn't know what the berm on the northwest side of the site was.



ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION Dee W. Lloyd	SIGNATURE <i>Dee W Lloyd</i>	DATE 2-19-93
--	---------------------------------	--------------

ACTION TAKEN

SIGNATURE	TITLE	DATE
-----------	-------	------