

START

CONVERSATION RECORD

TIME
1415DATE
17 MAR 93

TYPE <input type="checkbox"/> VISIT <input type="checkbox"/> CONFERENCE X TELEPHONE <input type="checkbox"/> INCOMING <input type="checkbox"/> OUTGOING			ROUTING	
			NAME/SYMBOL	INT
Location of Visit/Conference				
NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	ORGANIZATION (Office, dept., bureau, etc.)	TELEPHONE NO.		
Brian Dixon	KEH Hanford	509-376-7053		
SUBJECT				
1240 HWSA				

SUMMARY

I discussed 1240 HWSA location with Brian. The area on SW corner that was inspected has been there probably since 1951 as indicated on WIDS (Waste Info Data System). However, no Haz Waste was ever staged here, only hazardous materials. A RCRA Satellite area is located inside the building which collects Rags and PCB wastes. This satellite area was observed during the inspection, however, no waste was in the satellite area. Brian said that the satellite area had been moved to another location. Since the 1240 HWSA has 2 drains in the pad and isn't managed under RCRA it needs to be addressed under CERCLA.



ACTION REQUIRED

Update inspection summary to note that 1240 HWSA is not a RCRA satellite area. Correct WIDS Form for 1240 HWSA. Place 1240 HWSA in new site file.

NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE	DATE
DEE W. LLOYD	<i>Dee W Lloyd</i>	1-17-93

ACTION TAKEN

SIGNATURE	TITLE	DATE