




9100776  
0012923

STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

Mail Stop PV-11 • Olympia, Washington 98504-8711 • (206) 459-6000

February 15, 1991

Mr. Steven H. Wisness  
Hanford Project Manager  
United States Department of Energy  
P.O. Box 550  
Richland, Washington 99352



Re: Repair of Catch Tank S-302

Dear Mr. Wisness:

As agreed in the telephone conversation of February 15, 1991 between Mr. Gary Anderson of my staff and Mr. Erlandson and others of Westinghouse and DOE, I am writing this letter to approve the grouted repair of Catch Tank S-302-A on February 21, 1991. This approval to repair and use Catch Tank S-302-A is contingent on the following:

1. Batch designs for the non-shrink grout are given to his office in writing not later than March 21, 1991.
2. The test procedure for leak testing the grouted tank is given to this office in writing not later than March 21, 1991.
3. That Gary Anderson of my staff be given the opportunity to be present when this grouting operation takes place.

If you need to discuss this matter further, please call Gary Anderson of my staff at (206) 438-7558.

Sincerely,

Timothy L. Nord  
Hanford Project Manager  
Department of Ecology

cc: Brad Erlandson, WHC  
Dave Nylander, Ecology Kennewick  
T.B. Veneziano, AR

TLN:ga



**DISTRIBUTION COVERSHEET**

**Author**  
TL Nord/Dept. of Ecology

**Addressee**  
SH Wisness/DOE-RL

**Incoming Correspondence No.**  
9100776

**Subject** Repair of Catch Tank S-302-A

**Internal Distribution**

Approval	Date	Name	Location	w/att
		Correspondence Control	A3-01	
		BA Austin	B2-14	
		RJ Bliss		
		LC Brown	H4-51	
		CJ Geier	H4-57	
		KL Hoewing		
		RE Lerch (Assignee)		
		HE McGuire		
		K Parnell	H4-18	
		LL Powers	B2-35	
		SM Price	H4-57	
		FA Ruck, III	H4-57	
		KR Jordan		
		TB Veneziano	B2-35	
		BG Erlandson	B2-19	
		RD Wojtasek	L4-92	
		<b>EDMC</b>	<b>H4-22</b>	
		TPAI File (DH)	B2-35	

