



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 10
HANFORD/INL PROJECT OFFICE
309 Bradley Boulevard, Suite 115
Richland, Washington 99352

1216949

September 18, 2012

Jonathan A. Dowell
Assistant Manager for the River and Plateau
U.S. Department of Energy
Richland Operations Office
PO Box 550
Richland, Washington 99352

Re: 200-ZP-1 Interim Pump and Treat Summary Performance Report for Calendar Year 2012
(DOE/RL-2012-08)

Dear Mr. Dowell:

The U.S. Environmental Protection Agency has received the *200-ZP-1 Interim Pump-and-Treat Summary Performance Report for Calendar Year 2012* (DOE/RL-2012-08). This report is intended to serve as the final remedial action report for the 200-ZP-1 OU interim remedial action. This remedial action is identified in the *Record of Decision for the USDOE Hanford 200-ZP-1 Operable Unit* (1995). Under the interim remedial action, a pump-and-treat system to address the shallow portion of the aquifer (upper 15 ft) in the 200-ZP-1 OU was operated from 1996 to 2012 to remove carbon tetrachloride contamination from the highest concentration area of the contaminant plume.


Upon review of the document, the EPA agrees that this document serves as the final remedial action report for the 200-ZP-1 OU interim remedial action.

If you have any questions, please feel free to contact Emerald Laija at 509-376-4919.

Sincerely,

Dennis Faulk, Program Manager
Hanford Project Office

cc: Jane Hedges, Ecology
Susan Leckband, HAB
Ken Niles, ODOE
Stuart Harris, CTUIR
Gabriel Bohnee, Nez Perce Tribe
Russell Jim, Yakama Nation
Admin Record, 200-ZP-1



200-ZP-1