

# START

86.11.17

0028113

**Westinghouse Hanford Company  
Post Office Box 1970  
Richland, Washington 99352**

Fax Number: (509) 376-2816

FTS Number: 444-2816

Verify Number: (509) 376-0614

FTS Verify Number: 444-0614

Date: 2/2/93

Number of Pages: 2

To: DAN DUNCAN

Phone: (206) 553-6693

Location: EPA SEATTLE

Fax Number: (206) 553-8509

From: STEVE SKURLA

Phone: (509) 372-1102

Message: \_\_\_\_\_

DAN, PLEASE HAVE CATNY CHECK OUT THIS  
TEXT. LET ME KNOW IF IT IS ACCEPTABLE.  
WE ARE HOLDING CERTIFICATION UNTIL WE  
HEAR FROM YOU - THANKS Steve

93129360748



93129160749

<sup>WAS BEEN</sup>  
Contaminated equipment, or other secondary waste not returned to the LERF, that ~~is~~ destined for treatment and/or disposal will be placed in containers with necessary labelling and maintained in a satellite accumulation area until the container is filled. When the container is filled, the waste generation date will be marked on the container and the container will be moved to a RCRA compliant less than 90-day storage area pending waste designation. Upon designation of the containerized waste, additional labelling will be placed on the container as necessary and the waste will be transferred to a Hanford ~~Site~~ treatment, storage, or disposal unit per Hanford ~~Site~~ procedures.

<sup>1</sup>  
FACILITY

<sup>1</sup>  
FACILITY

TEXT TO SUBSTITUTE FOR  
TEXT ON P. 4-31

# MESSAGE CONFIRMATION

DATE:02/02/93 TIME:09:03

ID:

DATE	TIME	TX-TIME	DISTANT STATION ID	MODE	PAGES	RESULT
02/02	09:02	00'59"	2065532509	G3-S	002	OK

93129360710