

## Waste Site Reclassification Form

0521031

<p><b>Date Submitted:</b> 2/17/2000</p> <p><b>Originator:</b> F. M. Corpuz</p> <p><b>Phone:</b> 373-1661</p>	<p><b>Operable Unit(s):</b> 100-DR-1</p> <p><b>Waste Site ID:</b> 116-D-3 Crib</p> <p><b>Type of Reclassification Action:</b></p> <p>Rejected <input checked="" type="checkbox"/></p> <p>Closed Out <input type="checkbox"/></p> <p>No Action <input type="checkbox"/></p>	<p><b>Control Number:</b> 2000-02</p> <p><b>Lead Agency:</b> Ecology</p>
--	--	--

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

Based upon excavations, a review of Hanford Site drawings, ground penetrating radar (GPR) investigations, discussions with field personnel and the original design team, and reference drawing H-1-3091, it has been determined that the 116-D-3 Crib and the 116-D-4 Crib are actually the same site. The 116-D-3 (108-D crib #1) site was identified as a french drain in the Technical Baseline Report for the 100-D Area; however, this identification was based on drawings that were not as-built. Both the 116-D-3 and 116-D-4 sites are listed in WIDs as cribs for the 108-D Shipping Cask Handling Facility.

**Basis for reclassification:**

The 116-D-3 Crib is actually the same site as the 116-D-4 Crib. Remediation activities at 116-D-4 took place on October 20 - 21, 1999. Reference drawing H-1-3091 indicates that the 116-D-3 is co-located with 116-D-4 at coordinates N151757, E573832. The possibility of 116-D-3 being a separate site has been investigated through excavation at all historically reported locations. Initial excavation at the contract design coordinates (N151739, E573774) occurred on 10/20/99; however, the excavation showed no engineered structure or contamination (using field instruments). Excavation activities occurred on 11/4/99 at location coordinates N151757, E 573768, which is also referenced as a possible location for 116-D-3. No evidence of a structure or contamination (using field instruments) was found. Excavation also occurred on 12/30/99 at coordinates N151725, E573807 and N151731, E573832. No structures or contamination (using field instruments) were found. The basis for reclassification is further described in *Environmental Restoration Contractor Meeting Minutes - GPR/Field Investigation Issues for Group 3 Remedial Design, CCN 037771*, dated November 21, 1996.

Glenn I. Goldberg  
DOE Project Manager

Wayne Scott  
Ecology Project Manager

N/A  
EPA Project Manager

[Signature]  
Signature

[Signature]  
Signature

3/20/00  
Date

4-6-00  
Date

          
Date

RECEIVED  
JUN 19 2000

EDMC