

# START

0036668

NUCLEAR AND MIXED WASTE MANAGEMENT PROGRAM  
HANFORD PROJECT

224-T TRUSAF

PHOTOGRAPH LOG

PHOTOGRAPHS TAKEN ON JANUARY 7, 1994 BY ALISA D. HUCKABY



NUMBER	COMMENTS:
1	Film advanced, no photo.
2	Photo of previous crack in receiving area.
3	Photo of damaged sealant (from fork lift).
4	Photo of crack in wall extending upward from floor. Photo taken near receiving area door located near southeastern corner of building.
5	Photo of sealant bubble located near door near x-ray room. Door located near southwestern end of building.
6	Photo of crack in floor near assayer control room and storage unit operations office. Crack shown in photo represents unsealed portion of pre-existing rectangular shaped crack.
7	Photo of crack in floor extending across entrance to assayer control room and storage unit operations office.
8	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
9	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
10	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
11	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
12	Photo of seam and sealed areas in floor of first floor hall (northern end of hall) north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).

9413224.1390

START



**THIS PAGE INTENTIONALLY  
LEFT BLANK.**

THIS PAGE INTENTIONALLY LEFT BLANK.

THIS PAGE INTENTIONALLY LEFT BLANK.

13	Photo of cracks and what appears to be a sealed pipe in floor of first floor near elevator located on northwestern end of building.
14	Photo of crack in floor of first floor just outside of elevator located on northwestern end of building.
15	Photo of "penetration" holes on second floor near elevator near column labelled "D-3."
16	Photo of "penetration" holes on second floor near elevator near column labelled "D-3."
17	Photo of scratch (from fork lift) in sealant on second floor near column labelled "D-3."
18	Photo of scratch in sealant on second floor near column labelled "C-3."
19	Photo of "penetration" holes on second floor near column labelled "C-5."
20	Photo of bubbles in sealant on second floor near columns labelled "C-5" and "C-6."
21	Photo of "penetration" hole on second floor between columns labelled "D-5" and "D-6."
22	Photo of damage in sealant on second floor near column labelled "D-5."
23	Photo of damage in sealant on second floor near column labeled "C-3."
24	Photo of "penetration" hole on second floor near door labeled "208" located on the southwestern end of the building.

9413224.1391

**THIS PAGE INTENTIONALLY  
LEFT BLANK**

E Mail to Barbara Neff of the Administrative Record, H6-08.

Hi Barbara,

Would you please enter the January 7, 1994 photographs I'm sending (via mail stop system) onto the administrative record for 224-T TRUSAF. If you have any questions, please give me a call at 736-3034.

Thanx, Alisa Huckaby

9113224.1392

Barbara, Debbie,

This have been stamped and is being sent through the system 6/16/94. 0036668




Kim

Middle July

THIS PAGE INTENTIONALLY  
LEFT BLANK

SPRINT

9413224.1393





January 7, 1994 224-T TRUSAF  
200 West Area Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 2

JANUARY 7, 1994 224-T TRUSAF  
200 West Area Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 3

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 4

9113224-1394

9413224.1395



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

5

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

6

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967




Photo taken by A.D. Huckaby

Photo #

7

9113224-1396

9413224.1397



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo #

8

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

9

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967




Photo taken by A.D. Huckaby

Photo #

10

9113224-1398

9413224.1399



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

11

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 12




January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 13

911 3224-1400

944 3224.1401



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo #

14

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo #

15

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby




Photo #

16

9113224-1402

9113224-1402

9113224.1403



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 17

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 18



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 19

9113221-1404

9113224.1405



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 20



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 21

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 22

9113224-1406

2041-4558119

911 3224.1407



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 23

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 24

911 3224-1408

911 3224-1408

STOCK PHOTO





94 1 7

January 7, 1994 224-T TRUSAF  
200 West Area Hanford Site-DOE  
WA 789008967  
Photo taken by A.O. Huckaby  
Photo # 2

JANUARY 7, 1994 224-T TRUSAF  
200 West Area Hanford Site-DOE  
WA 789008967  
Photo taken by A.O. Huckaby  
Photo # 3


January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 4



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 5

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 6

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 7



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo # 8

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby


Photo # 10

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo # 9



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 11

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 12

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 13




SILOUETTE PHOTOGRAPHY

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 14

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 16

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 15



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

17

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

18


January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

19

STOCK # PPVH46-000



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 20

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 21

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 22

STOCK# PPVH46-000



January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 23

January 7, 1994 224-T TRUSAF  
200 West Area, Hanford Site - DOE  
WA 7890008967  
Photo taken by A.D. Huckaby  
Photo # 24