

0090457



Department of Energy
Richland Operations Office
P.O. Box 550
Richland, Washington 99352

10-EMD-0099

SEP 17 2010

Ms. G. P. Davis
Nuclear Waste Program
State of Washington
Department of Ecology
3100 Port of Benton Boulevard
Richland, Washington 99354

Dear Ms. Davis:

HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA)
PERMIT UNDERGROUND PIPE MAPPING AND MARKING REPORT FOR 2010 (PERMIT
CONDITIONS II.U AND II.V)

Enclosed is the annual notification of updates made to the dangerous waste underground pipeline maps for the 2010 reporting period (April 1, 2009, through March 30, 2010) in accordance with Hanford Facility RCRA Permit, WA7 89000 8967 (Permit) Conditions II.U.3 and II.U.4. The maps that required updating are identified in the report. Copies of the maps are available on the Hanford Site via the Hanford Document Management and Control System.

No marking activities, as required by Permit Condition II.V, were conducted during the reporting period (April 1, 2009, through March 30, 2010). As noted in the submittals for 2003 through 2009, a portion of the 200 East Area boundary fence remains down in support of the Waste Treatment and Immobilization Plant construction. This portion of fence had been marked as required by Permit Condition II.V to identify the location of the underground pipeline associated with the 216-B-3 Pond. When the fence is replaced and new boundaries are established, the 216-B-3 Pond pipeline markings will be reviewed to ensure compliance with Permit Condition II.V.

If you have any questions, please contact me, or your staff may contact Ray J. Corey, Assistant Manager for Safety and Environment on (509) 376-0108.

Sincerely,

A handwritten signature in black ink, appearing to read "Matt McCormick".

Matt McCormick
Manager

EMD:ACM

Enclosure

cc w/encl: See Page 2

RECEIVED
SEP 22 2010

EDMC

H.O.1

D.1.2, D.2.8, S.2.3, S.2.4, D.2.5

Ms. G. P. Davis
10-EMD-0099

-2-

cc w/encl:

W. J. Taylor, ORP
Environmental Portal, LMSI, A3-95
Ecology NWP Library
HF Operating Record (S. Thompson, MSA, H7-28)
Administrative Record, H6-08 (H-0-1)

cc w/o encl:

M. N. Brosee, WCH
L. L. Fritz, MSA
J. A. Hedges, Ecology
J. G. Lehew, CHPRC
J. D. McDonald, Ecology
E. R. Skinnarland, Ecology
C. G. Spencer, WRPS
C. L. Whalen, Ecology

ENCLOSURE

**Hanford Facility Mapping and Marking of Dangerous Waste Underground Pipelines
2010 Annual Notification**

(Permit Conditions II.U and II.V)

Consisting of 2 pages, including cover sheet

**Hanford Facility Mapping and Marking of Dangerous Waste Underground Pipelines
2010 Annual Notification
(Permit Conditions II.U and II.V)**

The following is a list of maps revised for the 2010 reporting period (April 1, 2009 through March 30, 2010). This listing is provided in accordance with Hanford Facility Resource Conservation and Recovery Act Permit, WA7 89000 8967 (Permit) Condition II.U.4. These maps are for Permit Condition II.U uses only, and not for establishing unit specific treatment, storage, and disposal (TSD) unit boundaries. Refer to the Hanford Facility Part A Form for the TSD unit boundaries.

Drawing	Title	Sheet	Revision	Engineering Change Notice
H-1-83080	TSD Unit D-1-2 1301-N/1325-N Liquid Waste Disposal Facility	Sheet 1	Rev. 3	
H-1-83082	1301-N Liquid Waste Disposal Facility Map Attachment Report	Sheet 1	Rev. 2	
H-2-827324	TSD Unit: D-2-8, 216-U-12 Crib	Sheet 1	Rev. 1	
H-13-000275	S SX SY U Tank Farms TSD Units (S-2-3) and (S-2-4)	Sheet 1	Rev. 3	ECN-725981-RO
H-13-000275	S SX SY U Tank Farms TSD Units (S-2-3) and (S-2-4)	Sheet 2	Rev. 2	ECN-727261-RO

Note: In Fiscal Year (FY) 2009, 216-U-12 Crib was, reclassified from a treatment, storage, and disposal (TSD) unit to a past practice unit. The 2009 report inadvertently stated that the maps would be deleted. In 2010, H-2-827324 was updated to reflect pipeline removal.

In FY 2010, 216-A-10 Crib was, reclassified from a TSD unit to a past practice unit.