




## Department of Energy

Richland Operations Office  
P.O. Box 550  
Richland, Washington 99352

91-EAB-015

MAR 1 1991



Mr. Daniel Willey, Compliance Officer  
State of Washington  
Department of Ecology  
Hanford Project Office  
7601 West Clearwater Ave., Suite 102  
Kennewick, Washington 99336

Dear Mr. Willey:

### THE 2711-E STEAM CLEANING PAD STATUS AND CORRECTIVE ACTIONS

This letter is in follow-up to the January 17, 1991, meeting held between yourself, Mr. Osweiler, representatives from the U.S. Department of Energy, Richland Operations Office (DOE-RL) and the Westinghouse Hanford Company (WHC). The following items were discussed in our meeting and are being reiterated here for the sake of clarity:


- The 2711-E Steam Cleaning Pad is no longer in operation and will not be operated until the rinsate discharge system has been retrofitted.
- It is proposed that the steam cleaning pad be modified in such a manner as to collect the rinsate rather than discharge it to the french drain. The accumulated rinsate could be sampled, and subsequent to analysis, be transferred to the 1100 Area for discharge to a Public Operated Treatment Works.
- The need for remediation of the french drain serving the steam cleaning sump will be based on sample analysis results. If remediation is deemed necessary, then it is proposed that the 2711-E Steam Cleaning Pad remediation be evaluated as part of the 200-SS-1 operable unit evaluation.
- As discussed, the process discharges from the 200 East Area Equipment Maintenance Facility (2711-E Facility), located just southeast of the 2711-E Steam Cleaning Pad, are also of interest to the State of Washington Department of Ecology. The enclosed drawing provides details of all process discharges from this facility. Also enclosed is a description of the highlighted areas of the drawing.



As stated, the sampling of the sump sludge will be scheduled as soon as the proper arrangements and procedures have been provided for.


In the interim, any questions concerning the above discussion can be directed to Ms. D. J. Williams, DOE-RL, on (509) 376-8488; or Mr. B. G. Erlandson, WHC, on (509) 376-5969.

Sincerely,



R. D. Izatt, Director.  
Environmental Restoration Division  
Richland Operations Office

ERD:DJW



R. E. Lerch, Manager  
Environmental Division  
Westinghouse Hanford Company

Enclosure:  
Drawing H-2-93802 -- 2711E



## CORRESPONDENCE DISTRIBUTION COVERSHEET

Author

Addressee

Correspondence No.

M. J. Hall, 6-3664

Mr. D. Willey, Ecology

Incoming 9100793

Subject: THE 2711-E STEAM CLEANING PAD STATUS AND CORRECTIVE ACTIONS

### INTERNAL DISTRIBUTION

Approval	Date	Name	Location	w/att
		Correspondence Control	A3-01	
		M. R. Adams	H4-55	
		R. J. Bliss	B3-04	
		L. C. Brown	H4-51	
		W. R. Brown	B2-19	
		G. D. Carpenter	B2-16	
		P. J. Davis	B2-19	
		L. P. Diediker	T1-30	
		B. G. Erlandson	B2-19	
		R. A. Evanoff	G4-10	
		H. E. Hager, Jr.	S4-60	
		M. J. Hall	B2-19	
		K. L. Hoewing	B3-06	
		L. G. Juguilon	B2-19	
		R. J. Landon	B2-19	
		R. E. Lerch (Assignee)	B2-15	
		A. J. Miskho	B2-19	
		A. D. Poor	G4-11	
		R. K. P'Pool	T1-30	
		W. J. Schlauder	G4-02	
		D. E. Stocker	G4-11	
		T. M. Wintczak	L4-92	
		EDMC	H4-22	
		MJH/LB	B2-19	

