



0054520

Department of Energy
Richland Operations Office
P.O. Box 550
Richland, Washington 99352

01-RCA-179

FEB 27 2001

Ms. L. E. Ruud, Permit Specialist
Nuclear Waste Program
State of Washington
Department of Ecology
1315 West Fourth Avenue
Kennewick, Washington 99336

RECEIVED
MAR 12 2001

EDMC

Dear Ms. Ruud:

2000 NONCOMPLIANCE REPORT FOR SUBMITTAL TO THE STATE OF WASHINGTON DEPARTMENT OF ECOLOGY (ECOLOGY) IN FULFILLMENT OF CONDITION I.E.19. OF THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT

Enclosed is the 2000 Noncompliance Report submitted in fulfillment of Condition I.E.19. of the Dangerous Waste Portion of the Hanford Facility RCRA Permit. This condition states, "The permittees shall report to the Department all instances of noncompliance not otherwise required to be reported elsewhere in this Permit at the time the Annual Dangerous Waste Report is submitted." Additionally, noncompliances with the permit conditions alleged by Ecology or reported by the permittees through Notices of Violation, Notices of Correction, Inspection Reports, Project Manager Meeting Minutes, or other written correspondence are excluded. The due date for the Annual Dangerous Waste Report to be submitted to Ecology is March 1, 2001.

The 2000 Noncompliance Report was compiled by Fluor Hanford, Inc. from input received from the U.S. Department of Energy, Richland Operations Office (RL) and Office of River Protection; Bechtel Hanford, Inc.; CH2M HILL Hanford Group, Inc.; and Pacific Northwest National Laboratory representatives. The 2000 Noncompliance Report covers the period from January 1, 2000, through December 31, 2000.

Ms. L. E. Ruud
01-RCA-179

-2-

FEB 27 2001

Should you have any questions regarding the contents of this letter or the enclosure, please contact A. C. McKarns, RL, on (509) 376-8981.



Joel Hebdon, Director
Regulatory Compliance and Analysis Division
DOE Richland Operations Office



Richard H. Gurske, Acting Director
Environment and Regulation
Fluor Hanford, Inc.



T. E. Logan
Vice President, Operations
Bechtel Hanford, Inc.



Roby D. Enge, Director
Environment, Safety, and Health
Pacific Northwest National Laboratory



W. T. Dixon, Director
Environmental Services
CH2M HILL Hanford Group, Inc.

Enclosure:
2000 Noncompliance Report

cc w/encl:

Administrative Record, H6-08

Ecology Library, Kennewick

Hanf. Fac. Op. Rec., H6-08

R. J. Landon, BHI

T. A. Wooley, CHG

J. H. Richards, CTUIR

M. A. Wilson, Ecology

D. R. Sherwood, EPA

S. B. Clifford, FHI

R. H. Engelmann, FHI

R. H. Gurske, FHI

Environmental Portal, LMSI

P. Sobotta, NPT

H. T. Tilden, PNNL

R. Jim, YN

ENCLOSURE

2000 Noncompliance Report

Consisting of 2 pages,
including cover page

2000 Noncompliance Report

Reporting Period: January 1, 2000, through December 31, 2000

Item	Co-Operator	Category	Permit Condition	Description	Corrective Action	Status
1	FH	Hanford Fire Department	II.B.1	A noncompliance existed following an accident involving a Hanford Fire Department "Grass Fire Unit" on June 27, 2000. The equipment list contained in DOE/RL/94-02, <i>Hanford Emergency Management Plan</i> , Appendix C requires 4 each "Grass Fire units."	The Grass Fire Unit was replaced by modifying a base unit from transportation. The modified base unit was placed into service on September 12, 2000. A replacement unit is planned for purchase in FY2001.	Complete
2	FH	Hanford Fire Department	II.B.1	A noncompliance existed following an accident involving Hanford Fire Department "Tender 91" on October 12, 2000. The equipment list contained in DOE/RL/94-02, <i>Hanford Emergency Management Plan</i> , Appendix C requires 1 each "Water Tender".	The Tender 91 truck will be replaced by renting a water truck in FY2001. Permanent replacement of the vehicle is planned.	Open
3	BHI	1325-N	II.C.1	The permit requires that the training records be maintained in the Facility Operating Record or on electronic data storage. Not all site-specific training records were maintained in accordance with the permit condition.	Training records were entered into the electronic database, which is part of the Facility Operating Record.	Complete
4	BHI	183-N (SAA)	II.I.1	The permit requires that a list be included in the Facility Operating Record that identifies the locations of satellite accumulation areas (SAA), and that amendments to the list be recorded within 7 working days after new information becomes available. The SAA at Building 183-N was moved to 186-N, along with the generator's activity but the list was not amended to reflect the new location.	The list was amended immediately upon discovery. Personnel will be reminded of the requirement to maintain an up-to-date list of SAA locations.	Complete