

START

9413299.0996

0039191



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

1315 W. 4th Avenue • Kennewick, Washington 99336-6018 • (509) 735-7581

October 17, 1994

Mr. Robert Holt
Acting Project Manager
U. S. Department of Energy
P.O. Box 550
Richland, WA 99352



Dear Mr. Holt:

Re: Part A Submittals 1301N, 1325N, 1324N and 1324N/A

The Washington State Department of Ecology has reviewed the above referenced Part A submittals and is transmitting its comments. The comments relating to each submittal follow the appropriate heading.

1301N Part A:

Page 2 of 7, Section III. C.

The process code of D84 (Surface Impoundment) has inadvertently been used. The process code of D81 (Landfill) more appropriately describes the activities which occurred at this unit and is consistent with the listing entered in section IV.

Page 3 of 7, Section IV

The dangerous waste code D007 is not included in the listing of constituents discharged to this unit, however, it is listed as having been discharged to the 1325N crib. Did operations change or is this simply an omission? Please revise the submission requiring correction.

1325N Part A:

Page 3 of 7, Section IV, line 4

The dangerous waste code D007 with an estimated annual quantity of 10,000 pounds was entered as having been discharged to this unit. This code is not reflected on Part A for the 1301N crib. What circumstance accounts for this discrepancy?

Mr. Robert Holt
October 17, 1994
Page 2

1324NA Part A

No comment.

1324N Part A

No comment.

Please revise the documents to reflect the above stated comments or provide the appropriate explanation. Should you have any questions please do not hesitate to contact me at (509) 736-3029.

Sincerely,



Phillip R. Staats
Unit Manager
Nuclear Waste Program

PS:skr

cc: Julie Erickson, USDOE
Bryan Foley, USDOE
Pam Innis, EPA

Administrative Record (~~100-NR-1, 100-NR-2~~)

D-1-2, T-1-2 per Phil Staats