

1243832

[0071511H]



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

3100 Port of Benton Blvd • Richland, WA 99354 • (509) 372-7950
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

April 18, 2017

17-NWP-043

Mr. Doug S. Shoop, Manager
Richland Operations Office
United States Department of Energy
PO Box 550, MSIN: A7-50
Richland, Washington 99352

Mr. Ty Blackford, President and CEO
CH2M HILL Plateau Remediation Company
PO Box 1600, MSIN: H7-30
Richland, Washington 99352

Re: Changes Required to the 207A South Retention Basin Closure Report, DOE/RL-2016-74, Revision 0
(207-A SRB Closure Report)

Dear Mr. Shoop and Mr. Blackford:

The Department of Ecology (Ecology) has completed our initial review of the 207-A SRB Closure Report. Ecology has determined that the submitted report contains errors.

Enclosed is a list of the errors and the corrections needed. The enclosed changes need to be included in the 207-A SRB Closure Report, for the report to be considered accurate and complete.

Once the changes are complete, you have two options for submitting the revised 207-A SRB Closure Report, with a letter to Ecology:

- Submit the pages with required changes, or
- Submit the entire revised 207-A SRB Closure Report.

Neither of these options require resubmission of the Owner/Operator or Co-Operator Certification of Closure, as long as the changes are completed as listed and letter 17-AMRP-0083, dated January 27, 2017 is referenced.


If there are any questions, please contact Tabitha Liebrecht, Permit Lead, at tabitha.liebrecht@ecy.wa.gov or (509) 372-7970, or Debra Alexander, Rev. 8C Permit Coordinator, at debra.alexander@ecy.wa.gov or (509) 372-7896.

Sincerely,

Suzanne Dahl
Dangerous Waste Permit Manager
Nuclear Waste Program

tal/aa
Enclosure

cc: See page 2



S-2-7



Mr. Shoop and Mr. Blackford
April 18, 2017
Page 2 of 2


17-NWP-043

cc electronic:

- Dave Bartus, EPA
- Dennis Faulk, EPA
- Ray Corey, USDOE
- Darin Corriell, CHPRC
- Laura Cusack, CHPRC
- Brian Dixon, CHPRC
- Ray Geimer, CHPRC
- Moses Jaraysi, CHPRC
- Deborah Singleton, CHPRC
- Jon Perry, MSA
- Ken Niles, ODOE
- Debra Alexander, Ecology
- Suzanne Dahl, Ecology
- Tabitha Liebrecht, Ecology
- Nina Menard, Ecology
- Cheryl Whalen, Ecology
- CHPRC Correspondence Control
- USDOE-RL Correspondence Control
- Environmental Portal
- Hanford Facility Operating Record

cc:

- Rod Skeen, CTUIR
- Gabriel Bohnee, NPT
- Russell Jim, YN
- Alyssa Buck, Wanapum
- Susan Leckband, HAB
- Administrative Record
- NWP Central File



ENCLOSURE

DOCUMENT REVIEW

Document: 207A South Retention Basin Closure Report (DOE/RL-2016-74, Revision 0)

1. **Page iii:** The title for Appendix I is inaccurate. It should read, "Analytical Report from Test America".
2. **Appendix E, Page E-1:** There are spelling errors in the Personnel section. P. Vopalinsky (Safety S&GRP) should be P. Vopalensky, and T. Mullan (Ecology) should be T. Mullin. These same errors are continued throughout Appendix E for P. Vopalensky and T. Mullin.
3. **Appendix G, Page G-73:** The Washington Certification number for GEL Laboratories, LLC is incomplete. The Certification number is C780-16. Please correct the error.
4. **Appendix I, Page I-i:** The appendix cover sheet incorrectly references Northwest Testing. The correct laboratory is Test America. Please correct the error.
5. **Appendix I:** The appendix is missing the Laboratory Certification information for Test America. Please include this information within the appendix, as it was for GEL Laboratories, LLC in Appendix G.

Note: It would be helpful for Ecology to see these changes in redline-strikeout before they are finalized and resubmitted to Ecology, to ensure the changes are what is needed to be accurate and complete.