



Department of Energy
Richland Operations Office
P.O. Box 550
Richland, Washington 99352

022605

OCT 10 1995

Mr. Steve M. Alexander
Perimeter Areas Section Manager
Nuclear Waste Program
State of Washington
Department of Ecology
1315 W. Fourth Avenue
Kennewick, Washington 99336-6018

Mr. Douglas R. Sherwood
Hanford Project Manager
U.S. Environmental Protection Agency
712 Swift Boulevard, Suite 5
Richland, Washington 99352-0539

Dear Messrs. Alexander and Sherwood:

DATA EVALUATION: 100-D PONDS, BHI-00328, REV. 01, (TSD D-1-1) PHASE II SAMPLING

Enclosed please find the subject document for your information. The revisions to this document include the State of Washington, Department of Ecology (Ecology), split data results generated as part of the Phase II sampling effort and the changes previously agreed upon in various coordination activities. The revisions have not changed any of the conclusions of the report and still indicate that the contamination at the D-Ponds exists only within the upper 0.6 to 1m (2 to 3 feet) of the settling pond bottom.

If you want to discuss this matter further or require additional information, please contact me on 376-9552, or Ms. Nicole Kimball on 376-4670.

Sincerely,

A handwritten signature in black ink, appearing to read "Glenn I. Goldberg", with a large, sweeping flourish extending to the right.

Glenn I. Goldberg, Project Manager
Remedial Actions Project

RAP:GIG

Enclosure

cc w/o encl:
G. R. Eidam, ERC
K. K. Holliday, Ecology
G. B. Mitchem, ERC

