



## Department of Energy

Richland Operations Office  
P.O. Box 550  
Richland, Washington 99352


90-ERB-121

SEP 27 1990

START

Mr. Paul T. Day  
Hanford Project Manager  
U. S. Environmental Protection Agency  
712 Swift Boulevard, Suite 5  
Richland, Washington 99352

Mr. Timothy L. Nord  
Hanford Project Manager  
State of Washington  
Department of Ecology  
Mail Stop PV-11  
Olympia, Washington 98504-8711



Dear Messrs. Day and Nord:

ERRATA TO PHASE 1 REMEDIAL INVESTIGATION REPORT FOR THE 1100-EM-1 OPERABLE UNIT

Enclosed are six revised pages (12 counting the backs of the pages) for the subject report. These pages should be inserted into the report sent you on August 30, 1990, to replace the pages as numbered.

These revised pages were provided to us at the 1100-EM-1 Unit Managers' Meeting on September 19, 1990, by Golder, Inc. (subcontractor to Westinghouse Hanford Company), who prepared the report. Copies were informally provided to U. S. Environmental Protection Agency and Washington State Department of Ecology representatives attending the meeting. Pages being replaced contain printing (font) errors, primarily incorrect measurement symbols.

We apologize for any inconvenience caused by the incorrect information. Please call Mr. R. K. Stewart of my staff on (509) 376-6192, if you have any questions about the revised pages or about the 1100-EM-1 Phase I Remedial Investigation Report.

Sincerely,

Steven H. Wisness  
Hanford Project Manager

ERD:RKS

Enclosure  
(4 sets, EPA)  
(6 sets, Ecology)

cc: On Reverse

cc w/encl:

J. C. Lehr, HQ, EM-42  
M. P. Leifer, HQ, EH-232  
H. Davidson, HAZWRAP  
J. Gasper, Argonne National Laboratory  
J. Burger, SWEC  
J. T. Stewart, USACE (8 copies)  
C. W. Malody, Advanced Nuclear Fuels Corp.

cc w/o encl:

T. M. Wintczak, WHC  
S. W. Clark, WHC  
W. Wright, Golder  
T. B. Veneziano, WHC

B2-35



# DISTRIBUTION COVERSHEET

<b>Author</b> SH Wisness/DOE-RL	<b>Addressee</b> PT Day TL Nord	<b>Correspondence No.</b> Incoming: 9004239
<b>Subject</b> Errata to Phase 1 Remedial Investigation Report for the 1100-EM-1 Operable Unit		

## Internal Distribution

Approval	Date	Name	Location	w/att
		Correspondence Control		
		President's Office		
		MR Adams	H4-55	
		BA Austin	B2-21	
		RJ Bliss		
		LC Brown	H4-51	
		SW Clark	H4-55	
		C DeFigh-Price	B2-20	
		KR Fecht	H4-56	
		VW Hall	B2-15	
		KL Hoewing		
		WL Johnson	H4-55	
		RE Lerch		
		HE McGuire (Assignee)		
		K Parnell	H4-18	
		DE Simpson		
		TB Veneziano	B2-35	
		JL Waite	B2-35	
		SA Wiegman	B2-19	
		TM Wintczak	B2-15	
		RD Wojtasek	B2-15	
		EDMC	H4-22	
		TPAI File (DH)	B2-35	
		Ref. 9003757		

