



Department of Energy
Richland Operations Office
P.O. Box 550
Richland, Washington 99352

0051563

071195

JUL 26 1999

Mr. Douglas R. Sherwood
Hanford Project Manager
U.S. Environmental Protection Agency
712 Swift Boulevard, Suite 5
Richland, Washington 99352-0539

Mr. E. R. Skinnarland
200 Area Section Manager
Nuclear Waste Program
State of Washington
Department of Ecology
1315 West 4th Avenue
Kennewick, Washington 99336-6018

RECEIVED
JUL 27 1999
BY DIS

Dear Messrs. Sherwood and Skinnarland:

PERFORMANCE EVALUATION REPORT FOR SOIL VAPOR EXTRACTION
OPERATIONS AT THE CARBON TETRACHLORIDE SITE, FEBRUARY 1992 –
SEPTEMBER 1998, BHI-00720, REV. 3

Attached is the subject document for your information. The purpose of this report is to evaluate both the soil vapor extraction system operating data and the effectiveness of soil vapor extraction in remediating the carbon tetrachloride contamination at the 200-ZP-2 Operable Unit.

This report updates the existing performance evaluation report, BHI-00720, Rev. 2, which covers the soil vapor extraction operation period February 1992 through June 1997.

If you have any questions, please contact me at 373-9631.

Sincerely,

Arlene C. Tortoso, Project Manager
Groundwater Project

GWP:ACT

Attachment

cc: See page 2

071195

Messrs. Sherwood and Skinnarland

-2-

JUL 26 1999

cc w/o attach:

G. C. Henckel, III, BHI

cc w/attach:

D. A. Faulk, EPA

D. N. Goswami, Ecology

M. K. Harmon, EM-442