



1248729

[00659964]

P.O. Box 1970 Richland, WA 99352

March 15, 1995

9551454

Mr. O. A. Farabee, Acting Director
Transition Programs Division
U.S. Department of Energy
Richland Operations Office
Richland, Washington 99352

Dear Mr. Farabee:

COMPLETION OF MILESTONE M-80-00-T02 FOR THE URANIUM TRIOXIDE PLANT

Attachment 1 is the list of hazardous substances remaining within the Uranium Trioxide Plant (UO₃) at the completion of deactivation as required in the Hanford Federal Facility Agreement and Consent Order (Tri-Party Agreement) milestone M-80-00-T02.

Transmittal of this report and turnover of the UO₃ Plant to Bechtel Hanford Incorporated to initiate the surveillance and maintenance phase completes the Tri-Party Agreement milestone M-80-00-T02.

Attachment 2 is a letter for your transmittal to State of Washington Department of Ecology and the U.S. Environmental Protection Agency to transmit these results.

If you have any questions, please call G. J. LeBaron at 373-1792 or L. C. Zinsli at 373-4134.

Very truly yours,

D. G. Hamrick, Director
PUREX/UO₃ Transition Project
Transition Projects Division

jft

Enclosures 2

RL - w/o enclosures
J. E. Mecca
L. D. Romine
A. H. Wirkkala

