

**TRI-PARTY AGREEMENT**

Change Notice Number TPA-CN- 630	TPA CHANGE NOTICE FORM	Date: 6/5/2014
Document Number, Title, and Revision: DOE/RL-2004-77, Removal Action Work Plan for 300 Area Facilities, Rev. 2		Date Document Last Issued: December 2007
Originator: R. F, Guercia, DOE/RL		Phone: (509) 376-5494

**Description of Change:**

Removal Action Work Plan for 300 Area Facilities (RAWP), DOE/RL-2004-77, Rev. 2 documents activities to be performed to achieve the non-time-critical removal action (NTCRA) for surplus facilities located in the 300 Area of the Hanford Site. The removal process is achieved through the deactivation, decontamination, decommissioning, and demolition (D4) of surplus facilities. This Change Form modifies the RAWP Appendix B, Air Monitoring Section, Section B.2, Airborne Source Information

R.F. Guercia DOE and D. A. Faulk Lead Regulatory Agency agree that the proposed change

Modifies an approved work plan/document and will be processed in accordance with the Tri-Party Agreement Action Plan, Section 9.0, *Documentation and Records*, and not Chapter 12.0, *Changes to the Agreement*.


The following changes is authorized (reference attachment):

- Appendix B, Section B.21, is modified to remove the requirement to submit a facility environmental hazards summary in lieu of an emissions estimate for those facilities with no appreciable radiological contamination.

Note: Double underline text indicates additions, strike-through indicates deletions.

**Justification and Impacts of Change:**

It is agreed that submittal of a facility environmental hazards summary in lieu of an emissions estimate is an obsolete requirement. Pre-demolition characterization continues to be performed and establishes the basis for when a radioactive air emissions estimate is required.



<b>Approvals:</b>		
R.F. Guercia	<u>6/5/14</u>	<input checked="" type="checkbox"/> Approved <input type="checkbox"/> Disapproved
DOE Project Manager	Date	
	<u>6/5/14</u>	<input checked="" type="checkbox"/> Approved <input type="checkbox"/> Disapproved
EPA Project Manager	Date	
D. A. Faulk		<input type="checkbox"/> Approved <input type="checkbox"/> Disapproved
NA		
Ecology Project Manager	Date	

1218523

## TPA-CN 630 Attachment

### Appendix B, Air Monitoring Section, Section B.2, AIRBORNE SOURCE INFORMATION

In addition, many of the facilities identified within the RAWP are believed to have little or no radiological contamination based on historical data reviews. The PTE from facilities with no appreciable radiological contamination is negligible. ~~In lieu of an emissions estimate, a summary of the facility environmental hazards will be provided to EPA for their review and approval that an emissions estimate is not required.~~ Historical data, characterization sampling, and scoping surveys are used to determine if contamination is present at levels that require an emissions estimate. For those facilities without an emissions estimate, if ~~if~~ however, contamination is discovered during D4 activities, an emissions estimate will be prepared and provided to EPA for review and approval.