

Waste Site Reclassification Form

Date Submitted: 4/26/2004	Operable Unit(s): 200-SW-2	Control Number: 2004-053
Originator: C. R. Webb	Waste Site ID: UPR-200-W-45	
Phone: 373-5573	Type of Reclassification Action:	
	Rejected: <input type="radio"/>	
	No Action: <input checked="" type="radio"/>	
	Interim Closed Out: <input type="radio"/>	
	Closed Out: <input type="radio"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

On November 6, 1957, a burial box containing ruthenium contaminated process equipment from REDOX collapsed and released contamination throughout 200 West Area. The release consisted of a cloud of contamination from the collapse of a burial box containing equipment contaminated with ruthenium-106. The contamination spread outside the burial ground and over a large area of ground inside and outside the 200 West Area.

Basis for reclassification:

The exact location of this release cannot be determined from the original documentation of the event. The release is not marked or posted. It is recommended the site be reclassified to No Action because the ruthenium-106 has decayed below detection levels.

The half life of ruthenium-106 is 372.5 days

<i>STEVE BOONESS</i>	<i>[Signature]</i>	<i>5/6/04</i>
DOE Project Manager	Signature	Date
<i>John B. Price</i>	<i>[Signature]</i>	<i>5/6/04</i>
Ecology Project Manager	Signature	Date
_____	_____	_____
EPA Project Manager	Signature	Date