



1231984
[0079225H]

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

3100 Port of Benton Blvd • Richland, WA 99354 • (509) 372-7950

711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

December 3, 2015

15-NWP-206

By certified mail

Ms. Stacy Charboneau, Manager
Richland Operations Office
United States Department of Energy
PO Box 550, MSIN: A7-50
Richland, Washington 99352

Mr. John A. Ciucci, President and CEO
CH2M HILL Plateau Remediation Company
PO Box 1600, MSIN: H7-30
Richland, Washington 99352

Re: Response to Area of Non-compliance from the T Plant Complex Dangerous Waste Compliance Inspection, Nuclear Waste Program Compliance Index No. 15.513

1231760

Reference: Submittal to Ecology, Receipt of Regulatory Requested Documents, dated November 12, 2015, from C. Clark, M. Collins, T. McKarns, USDOE-RL, and J. Williams, CHPRC, "Response to the State of Washington Department of Ecology (Ecology) Letter 15-NWP-199, 'Response to Areas of Non-Compliance from the T Plant Complex Dangerous Waste Compliance Inspection, Compliance Item 4,' dated November 9, 2015 – T Plant Operation Logbook dated 11-11-2015"

Dear Ms. Charboneau and Mr. Ciucci:

The Department of Ecology (Ecology) conducted a dangerous waste compliance inspection at the T Plant Complex on January 22, 2015, to determine compliance with the Washington State Dangerous Waste Regulations (Chapter 173-303 Washington Administrative Code). The regulations establish a system for safe and responsible management of dangerous waste.


During this inspection, several areas did not comply with the Dangerous Waste Regulations. The areas of non-compliance were provided to you in the Compliance Report, NWP Compliance Index No. 15.513, dated June 11, 2015. Compliance Problem No. 4 listed in the report identified the failure to include the date and nature of any repairs or remedial actions taken on the October 7, 2014, 214-T Building inspection record. The action required to address this non-compliance remained open.

After reviewing the above-listed U.S. Department of Energy and CH2M HILL Plateau Remediation Company response submittal, Ecology is satisfied that the action taken is sufficient to close out this non-compliance.

If you have questions, need to request an extension, or need further information, please contact me at nancy.ware@ecy.wa.gov or (509) 372-7912.

Sincerely,

Nancy Ware
Dangerous Waste Compliance Inspector
Nuclear Waste Program



tkb

cc: See page 2



Ms. Charboneau and Mr. Ciucci
December 3, 2015
Page 2 of 2

15-NWP-206
T Plant Complex
RCRA Site ID: WA7890008967
NWP Compliance Index No.: 15.513
Inspection Date: January 22, 2015

cc electronic:

Dave Bartus, EPA
Jack Boller, EPA
Dennis Faulk, EPA
Cliff Clark, USDOE
Michael Collins, USDOE
Tony McKarns, USDOE
Laura Cusack, CHPRC
Joel Williams, Jr., CHPRC
Jon Perry, MSA
Ken Niles, ODOE
Debra Alexander, Ecology
Kathy Conaway, Ecology
Suzanne Dahl, Ecology
Kelly Elsethagen, Ecology
Edward Holbrook, Ecology
Stuart Luttrell, Ecology
Jared Mathey, Ecology
John Price, Ecology
Debra Singleton, Ecology
Ron Skinnarland, Ecology
Nancy Ware, Ecology
Environmental Portal
Hanford Facility Operating Record

cc: Rod Skeen, CTUIR
Gabriel Bohnee, NPT
Russell, Jim, YN
Steve Hudson, HAB
Administrative Record
CHPRC Correspondence Control
NWP Central File
NWP Compliance Index File: 15.513
NWP Reader File

