

[0079924H]

FACILITY STATUS CHANGE FORM (for DOE/RL-2010-34 Facilities)

Date Submitted: September 22, 2015 Originator: Chris Strand Phone: 554-2720	Area: 300 Area Facility ID: MO-868 Action Memorandum: Hanford General Decommissioning	Control #: D4-300-103
---	---	---------------------------------

This form documents agreement among the parties listed below on the status of the facility D&D operations and the disposition of underlying soil in accordance with the applicable regulatory decision documents.

Section 1: Facility Status

- All removal actions require by action memo complete.
- Removal actions required by actions memo partially complete, remaining operations deferred.

Description of Completed Activities and Current Conditions:


Deactivation: Utility isolations were performed on the facility prior beginning removal actions.

Decontamination and Decommissioning: Hazardous materials were removed, which included oils (door actuators), grease, refrigerant, and lights/lamps. No asbestos containing materials were identified through inspection and testing. Hazardous material removal and waste disposition was performed in accordance with the *Removal Action Work Plan for River Corridor General Decommissioning Activities* (DOE/RL-2010-34, Rev. 2).

Demolition: Mobile office MO-868 was transported to ERDF on June 23, 2015, for disposal.

Description of Deferral (as applicable):

N/A



Section 2: Underlying Soil Status

- No waste site(s) present. No additional actions anticipated.
- Documented waste site(s) present. Cleanup and closeout to be addressed under Record of Decision.
- Potential waste site discovered during removal action. Waste site identification number <to be> assigned. Cleanup and closeout to be addressed under Record of Decision.

Description of Current/As-Left Conditions:

No excavation or backfill was associated with removal of MO-868. The location of the trailer remains asphalted.

Identification of Documented Waste Site(s) or Nature of Potential Waste Site Discovery (as applicable):

None.

Section 3: List of Attachments

1. Facility information (history and characterization).
2. Project photographs.

FACILITY STATUS CHANGE FORM (for DOE/RL-2010-34 Facilities)

	9/22/2015
DOE-RL (Lead Agency)	Date

DISTRIBUTION:

DOE: Rudy Guercia A3-04

Document Control, H4-11

Administrative Record, H6-08 (300-FF-2)

SIS Coordinator: Ben Cowin H4-22

D4 EPL: Chris Strand L1-15

Sample Design/Cleanup Verification: Theresa Howell H4-23

FR Engineering: Eric Ison L1-15

FR EPL: Chris Strand L1-15

Attachment 1: Facility Information

Building History

The MO-868 Trailer was a single-wide transportable facility. Typical mobile office construction consisted of sheet metal and wood walls and roof on a steel frame and encompassed approximately 265 square feet.

The MO-868 Trailer was first located at the 100N Area in 2005 and was used as a radiological count-room and later as a change trailer. The trailer was relocated to the 300 Area in 2014 where it was located in the 300 Area parking lot southwest of the 325 Building. The trailer supported 300 Area Industrial Hygiene personnel until removal in 2015.

Building Characterization:

Table 1 summarizes the industrial hygiene, radiological control, and asbestos samples collected in MO-868.

Table 1: Summary of Characterization Surveys at MO-868.

Type	Date	Documented In	Results Summary
Asbestos	May 21, 2012	CCN #165727	No asbestos identified.
Industrial Hygiene	July 22, 2014	IHEA-MO868-001	No hazards identified
Radiological Scoping Survey	July 31, 2013	RSR-100N-12-1704	No detectable contamination

Identification of Document Waste Sites:

No waste sites are associated with this mobile office.

Anomalies Discovered During Demolition:

No anomalies were discovered following removal of MO-868.

Attachment 2: Project Photographs

Photo 1: MO-868 as it appeared at the 100-N Area in 2006.



Photo 2: Former location of MO-866, September 2015.

