

Waste Site Assignment

WIDS Site Code: 2607-EF, Septic Tank West of 241-BX Tank Farm

Responsibility Assigned to (Contractor): C HPRC

Operable Unit (OU) or Waste Management Area (WMA): ~~200-MG-1~~ 200-MG-2 per Fred Rock CRW 11-6-09

Unit Category: RPP

Comments: The inactive septic system was connected to 271 BXR Control House, located inside the 241-BX tank farm fence.

DOE Federal Project Director: *[Signature]* Date: 11/4/09

Ecology Project Manager: *[Signature]* Date: 11/4/09

EPA Project Manager: _____ Date: _____

RECEIVED
DEC 02 2009
EDMC

WIDS Site Code: 2607-EF

3. Is the unit a waste disposal unit? (Complete items 3.a and 3.b below)	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
3.a Does the unit require a RCRA permit for the disposal of dangerous or mixed waste? Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	
3.b Have hazardous wastes or substances been disposed of in a burial ground, pit, pond, ditch, crib, trench, french drain, or land surface that is not subject to regulation as a RCRA disposal unit and may require action to mitigate a potential environmental impact (e.g., radioactive waste disposal units, pre-RCRA units)? Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	
If either 3.a or 3.b is YES, check YES for 3. If both are NO, check NO for 3. Go to 4.	
4. Is the unit an unplanned release that has not been adequately cleaned up and represents a potential threat to human health or the environment (i.e., releases above CERCLA reportable quantities defined in 40 CFR 302.4; other hazardous substance releases, including petroleum, that may require action to mitigate a potential environmental impact)?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
5. Is the unit an inactive, contaminated structure?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
6. Does the unit require a RCRA permit for the treatment or storage of dangerous or mixed waste?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
7. Is the unit another type of storage unit that may require action to mitigate a potential environmental impact (e.g., radioactive waste storage unit)?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>

If 2, 3, 4, 5, 6, or 7 is YES, check WASTE MANAGEMENT UNIT at the top of the first page of this form. If all are NO, check NOT A WASTE MANAGEMENT UNIT at the top of the first page.

Comments: The septic system was connected to the 271 BXR Control House. The building was located inside the 241-BX tank farm fence.

Christine Webb WIDS Investigator (Printed)	<i>Christine Webb</i> Signature	07/30/2008 Date
<i>James C. Rusk III</i> WIDS Regulatory Compliance (Printed)	<i>James C. Rusk III</i> Signature	8/14/08 Date
<i>J. A. Farabee</i> DOE Federal Project Director (Printed)	<i>J. A. Farabee</i> Signature	11/4/09 Date
<i>[Signature]</i> Ecology Project Manager (Printed)	<i>[Signature]</i> Signature	11/4/09 Date
_____ EPA Project Manager (Printed)	_____ Signature	_____ Date