

Waste Site Reclassification Form

Date Submitted: 11/10/2004 Originator: CR Webb Phone: 373-5573	Operable Unit(s): 200-RO-3 Waste Site ID: 296-S-1 Type of Reclassification Action: Rejected: <input checked="" type="radio"/> No Action: <input type="radio"/> Interim Closed Out: <input type="radio"/> Closed Out: <input type="radio"/>	Control Number: 2004-122
---	---	---------------------------------

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

The stack was built in 1950 to discharge filtered air from the south sample gallery and sample hoods of 202-S. The stack is attached to the outside south wall of the service portion of the south pipe gallery of 202-S.

Basis for reclassification:

The stack is attached to the 202-S building. The site should be Rejected (Consolidated) with the 202-S WIDS site.

<i>Fm Roddy</i> DOE Project Manager	Signature	11/10/04 Date
Ecology Project Manager	Signature	Date
<i>Craig Cameron</i> EPA Project Manager	Signature	11/10/04 Date