

Waste Site Reclassification Form

Date Submitted: 11/10/2004 Originator: CR Webb Phone: 373-5573	Operable Unit(s): 200-RO-2 Waste Site ID: 296-S-12 Type of Reclassification Action: Rejected: <input checked="" type="radio"/> No Action: <input type="radio"/> Interim Closed Out: <input type="radio"/> Closed Out: <input type="radio"/>	Control Number: 2004-123
---	--	---------------------------------


This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

The two stacks are located on the roof of the 276-S Building, over the operating gallery. The units received exhaust air from the 276-S Operating Gallery.

Basis for reclassification:

The stacks are located on the 276-S building. The stacks should be Rejected (Consolidated) with the 276-S WIDS site.

	Signature	
DOE Project Manager		Date
	Signature	
Ecology Project Manager		Date
EPA Project Manager	Signature	Date