

Waste Site Reclassification Form

Date Submitted: 11/2/2004	Operable Unit(s): 200-RO-3	Control Number: 2004-117
Originator: CR Webb	Waste Site ID: 296-S-6	
Phone: 373-5573	Type of Reclassification Action:	
	Rejected: <input checked="" type="radio"/>	
	No Action: <input type="radio"/>	
	Interim Closed Out: <input type="radio"/>	
	Closed Out: <input type="radio"/>	





This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

The stack is located on the roof in the northeast corner of 202-S. 296-S-6 was built to discharge unfiltered air from the silo gallery, organic feed tank and sample elevator.

Basis for reclassification:

The stack is attached to the 202-S building. The site should be Rejected (Consolidated) with the 202-S WIDS site.

		
DOE Project Manager	Signature	Date
Ecology Project Manager	Signature	Date
		
EPA Project Manager	Signature	Date