

## Waste Site Reclassification Form

<b>Date Submitted:</b> 12/13/2000	<b>Operable Unit(s):</b> 200-PO-3	<b>Control Number:</b> 2000-131
<b>Originator:</b> Ruthi Nelson	<b>Waste Site ID:</b> 241-AZ-151CT	
<b>Phone:</b> 372-2080	<b>Type of Reclassification Action:</b>	
	<b>Rejected:</b> <input checked="" type="radio"/>	
	<b>No Action:</b> <input type="radio"/>	
	<b>Interim Closed Out:</b> <input type="radio"/>	
	<b>Closed Out:</b> <input type="radio"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

The catch tank is located beneath the 241-AZ-151DS Diverter Station structure (Drawing H-2-67256). It was constructed as part of the diverter station structure.

**Basis for reclassification:**

The catch tank is part of the 241-AZ-151 Diverter Station structure. Information related to the catch tank should be consolidated with the 241-AZ-151DS Diverter Station WIDS file.

<i>Diane L. Clark</i> DOE Project Manager	<i>Diane L. Clark</i> Signature	<i>5-3-2004</i> Date
<i>[Signature]</i> Ecology Project Manager	<i>4-28-05</i> Signature	 Date
 EPA Project Manager	 Signature	 Date

**RECEIVED**  
OCT 09 2007

EDMC