

TestAmerica

THE LEADER IN ENVIRONMENTAL TESTING


ANALYTICAL REPORT

TestAmerica Laboratories, Inc.
TestAmerica Richland
2800 George Washington Way
Richland, WA 99352
Tel: (509)375-3131

TestAmerica Job ID: 300-8726-1
TestAmerica Sample Delivery Group: RL8726-1
Client Project/Site: I19-004

For:
CH2M Hill Plateau Remediation Company
825 Jadwin Avenue
Richland, Washington 99352

Attn: CPP Sample Management



Authorized for release by:
11/21/2018 12:17:56 PM

Ashley Worthy, Project Manager I
(509)375-3131
ashley.worthy@testamericainc.com



LINKS

Review your project results through
TotalAccess

Have a Question?



Visit us at:
www.testamericainc.com

I certify that this Certificate of Analysis is in compliance with the SOW, both technically and for completeness, for other than the conditions detailed in this package. Release of the data contained in this hard copy data package has been authorized by the Laboratory Manager, or a designee as verified by the attached signature.

The laboratory is accredited to EPA 7196A in Solid and Chemical Materials, per Washington State Department of Ecology this is approved for non-discharge water samples.

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13



Table of Contents

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Chain of Custody	5
Detection Summary	8
Client Sample Results	9
QC Sample Results	10
QC Association Summary	11
Lab Chronicle	12
Method Summary	14
Sample Summary	15
Receipt Checklists	16

Definitions/Glossary

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Qualifiers

General Chemistry

Qualifier	Qualifier Description
B	Estimated result. Result is less than the RL, but greater than MDL
U	Analyzed for but not detected.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
PQL	Practical Quantitation Limit
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)

Case Narrative

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Job ID: 300-8726-1

Laboratory: TestAmerica Richland

Narrative

**Job Narrative
300-8726-1**

Comments

No additional comments.

Receipt

The samples were received on 11/15/2018 2:30 PM; the samples arrived in good condition, properly preserved and, where required, on ice. The temperature of the cooler at receipt was 5.5° C.

General Chemistry

No analytical or quality issues were noted, other than those described in the Definitions/Glossary page.



CH2MHill Plateau Remediation Company		CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST				C.O.C.# I19-004-555		
Collector: Juan Aguilar /CHPRC		Contact/Requester: Karen Waters-Husted		Telephone No.: 509-376-4650				
SAF No.: I19-004		Sampling Origin: Hanford Site		Purchase Order/Charge Code: 300071				
Project Title: CERCLA, NOVEMBER 2018		Logbook No.: HNF-N-506-106139		Ice Chest No.: N/A				
Shipped To (Lab): TestAmerica Incorporated, Rich		Method of Shipment: GOVERNMENT VEHICLE		Bill of Lading/Air Bill No.: N/A				
Protocol: CERCLA		Priority: 30 Days		Offsite Property No.: N/A				
POSSIBLE SAMPLE HAZARDS/REMARK ** ** Contains Radioactive Material at concentrations that are not regulated for transportation per 49 CFR / IATA Dangerous Goods Regulations but are not releasable per DOE Order 458.1				SPECIAL INSTRUCTIONS N/A				
Sample No.	Filter	*	Date	Time	No/Type Container	Sample Analysis	Holding Time	Preservative
B3LTK8	N	W	11-15-18	0900	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C
B3LTK9	Y	W	11-15-18	0900	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C



300-8726 COC

8726-1
RL0726-1

Relinquished By: Juan Aguilar /CHPRC Signature: [Signature] Date/Time: NOV 15 2018 1220	Received By: Tim Callaway /CHPRC Signature: [Signature] Date/Time: NOV 15 2018 1220	Matrix * S = Soil DS = Drum Solids SE = Sediment DL = Drum Liquids SO = Solid T = Tissue SL = Sludge WI = Wipe W = Water L = Liquid O = Oil V = Vegetation A = Air X = Other	
Relinquished By: Tim Callaway /CHPRC Signature: [Signature] Date/Time: NOV 15 2018 1430	Received By: T. Holm /CHPRC Signature: [Signature] Date/Time: NOV 15 2018 1430		
Relinquished By: _____ Signature: _____ Date/Time: _____	Received By: _____ Signature: _____ Date/Time: _____		
Relinquished By: _____ Signature: _____ Date/Time: _____	Received By: _____ Signature: _____ Date/Time: _____		
FINAL SAMPLE DISPOSITION	Disposal Method (e.g., Return to customer, per lab procedure, used in process):	Disposed By:	Date/Time:

CH2MHill Plateau Remediation Company		CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST				C.O.C. # I19-004-551		
Collector: Juan Aguilar /CHPRC		Contact/Requester: Karen Waters-Husted		Telephone No.: 509-376-4650				
SAF No.: I19-004		Sampling Origin: Hanford Site		Purchase Order/Charge Code: 300071				
Project Title: CERCLA, NOVEMBER 2018		Logbook No.: HNF-N-506-106139		Ice Chest No.: N/A				
Shipped To (Lab): TestAmerica Incorporated, Rich		Method of Shipment: GOVERNMENT VEHICLE		Bill of Lading/Air Bill No.: N/A				
Protocol: CERCLA		Priority: 30 Days		Offsite Property No.: N/A				
POSSIBLE SAMPLE HAZARDS/REMARK ** ** Contains Radioactive Material at concentrations that are not regulated for transportation per 49 CFR / IATA Dangerous Goods Regulations but are not releasable per DOE Order 458.1				SPECIAL INSTRUCTIONS N/A				
Sample No.	Filter	*	Date	Time	No/Type Container	Sample Analysis	Holding Time	Preservative
B3LTK0	Y	W	11-15-18	1202	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C
B3LTJ9	N	W	11-15-18	1202	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C

Relinquished By: Juan Aguilar /CHPRC		NOV 15 2018 1220	Received By: Tim Calloway /CHPRC		NOV 15 2018 1220	Matrix * S = Soil DS = Drum Solids SE = Sediment DL = Drum Liquids SO = Solid T = Tissue SL = Sludge WI = Wipe W = Water L = Liquid O = Oil V = Vegetation A = Air X = Other
Relinquished By: Tim Calloway /CHPRC		NOV 15 2018 1430	Received By: J. Holm		NOV 15 2018 1430	
Relinquished By:			Received By:			
Relinquished By:			Received By:			
FINAL SAMPLE DISPOSITION	Disposal Method (e.g., Return to customer, per lab procedure, used in process):				Disposed By:	Date/Time:

8726
RL8726-1

Rev 0

November 21, 2018

CH2M Hill Plateau Remediation Company		CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST				C.O.C.# I19-004-553		
Collector: Juan Aguilar ICHPRC		Contact/Requester: Karen Waters-Husted		Telephone No.: 509-376-4650				
SAF No.: I19-004		Sampling Origin: Hanford Site		Purchase Order/Charge Code: 300071				
Project Title: CERCLA, NOVEMBER 2018		Logbook No.: HNF-N-506-106139		Ice Chest No.: N/A				
Shipped To (Lab): TestAmerica Incorporated, Rich		Method of Shipment: GOVERNMENT VEHICLE		Bill of Lading/Air Bill No.: N/A				
Protocol: CERCLA		Priority: 30 Days		Offsite Property No.: N/A				
POSSIBLE SAMPLE HAZARDS/REMARK ** ** Contains Radioactive Material at concentrations that are not regulated for transportation per 49 CFR / IATA Dangerous Goods Regulations but are not releasable per DOE Order 458.1				SPECIAL INSTRUCTIONS N/A				
Sample No.	Filter	*	Date	Time	No/Type Container	Sample Analysis	Holding Time	Preservative
B3LTK5	Y	W	11-15-18	0932	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C
B3M549	N	W	11-15-18	0932	1x60-mL aG	7196_CR6: COMMON	24 Hours	Cool <=6C

11/21/2018

Page 7 of 16

Page 7 of 16

8726
RL 8726-1

Relinquished By: Juan Aguilar ICHPRC Signature: [Signature] Date/Time: NOV 15 2018 1220	Received By: Tim Callaway ICHPRC Signature: [Signature] Date/Time: NOV 15 2018 1220	Matrix * S = Soil DS = Drum Solids SE = Sediment DL = Drum Liquids SO = Solid T = Tissue SL = Sludge WI = Wipe W = Water L = Liquid O = Oil V = Vegetation A = Air X = Other	
Relinquished By: Tim Callaway ICHPRC Signature: [Signature] Date/Time: NOV 15 2018 1438	Received By: [Signature] TARL Signature: [Signature] Date/Time: NOV 15 2018 1438		
Relinquished By: Signature: _____ Date/Time: _____	Received By: Signature: _____ Date/Time: _____		
Relinquished By: Signature: _____ Date/Time: _____	Received By: Signature: _____ Date/Time: _____		
FINAL SAMPLE DISPOSITION	Disposal Method (e.g., Return to customer, per lab procedure, used in process):	Disposed By:	Date/Time:

Detection Summary

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Client Sample ID: B3LTK8

Lab Sample ID: 300-8726-1

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.035		0.0040	0.0015	mg/L	1		7196A	Total/NA

Client Sample ID: B3LTK9

Lab Sample ID: 300-8726-2

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.035		0.0040	0.0015	mg/L	1		7196A	Total/NA

Client Sample ID: B3LTK0

Lab Sample ID: 300-8726-3

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.0027	B	0.0040	0.0015	mg/L	1		7196A	Total/NA

Client Sample ID: B3LTJ9

Lab Sample ID: 300-8726-4

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.0019	B	0.0040	0.0015	mg/L	1		7196A	Total/NA

Client Sample ID: B3LTK5

Lab Sample ID: 300-8726-5

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.021		0.0040	0.0015	mg/L	1		7196A	Total/NA

Client Sample ID: B3M549

Lab Sample ID: 300-8726-6

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Cr (VI)	0.020		0.0040	0.0015	mg/L	1		7196A	Total/NA

This Detection Summary does not include radiochemical test results.

TestAmerica Richland

Client Sample Results

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Client Sample ID: B3LTK8

Date Collected: 11/15/18 09:00

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-1

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.035		0.0040	0.0015	mg/L			11/15/18 16:32	1

Client Sample ID: B3LTK9

Date Collected: 11/15/18 09:00

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-2

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.035		0.0040	0.0015	mg/L			11/15/18 16:32	1

Client Sample ID: B3LTK0

Date Collected: 11/15/18 12:02

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-3

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.0027	B	0.0040	0.0015	mg/L			11/15/18 16:32	1

Client Sample ID: B3LTJ9

Date Collected: 11/15/18 12:02

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-4

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.0019	B	0.0040	0.0015	mg/L			11/15/18 16:33	1

Client Sample ID: B3LTK5

Date Collected: 11/15/18 09:32

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-5

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.021		0.0040	0.0015	mg/L			11/15/18 16:33	1

Client Sample ID: B3M549

Date Collected: 11/15/18 09:32

Date Received: 11/15/18 14:30

Lab Sample ID: 300-8726-6

Matrix: Water

General Chemistry

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.020		0.0040	0.0015	mg/L			11/15/18 16:33	1

QC Sample Results

Client: CH2M Hill Plateau Remediation Company
 Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
 SDG: RL8726-1

Method: 7196A - Chromium, Hexavalent

Lab Sample ID: MB 300-15899/3
 Matrix: Water
 Analysis Batch: 15899

Client Sample ID: Method Blank
 Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cr (VI)	0.0015	U	0.0040	0.0015	mg/L	-		11/15/18 16:28	1

Lab Sample ID: LCS 300-15899/4
 Matrix: Water
 Analysis Batch: 15899

Client Sample ID: Lab Control Sample
 Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec. Limits
Cr (VI)	0.250	0.257		mg/L	-	103	80 - 120

Lab Sample ID: 300-8726-2 MS
 Matrix: Water
 Analysis Batch: 15899

Client Sample ID: B3LTK9
 Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec. Limits
Cr (VI)	0.035		0.0501	0.0873		mg/L	-	104	75 - 125

Lab Sample ID: 300-8726-2 DU
 Matrix: Water
 Analysis Batch: 15899

Client Sample ID: B3LTK9
 Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	DU Result	DU Qualifier	Unit	D	RPD	RPD Limit
Cr (VI)	0.035		0.0355		mg/L	-	1	20

QC Association Summary

Client: CH2M Hill Plateau Remediation Company
 Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
 SDG: RL8726-1

General Chemistry

Analysis Batch: 15899

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
300-8726-1	B3LTK8	Total/NA	Water	7196A	
300-8726-2	B3LTK9	Total/NA	Water	7196A	
300-8726-3	B3LTK0	Total/NA	Water	7196A	
300-8726-4	B3LTJ9	Total/NA	Water	7196A	
300-8726-5	B3LTK5	Total/NA	Water	7196A	
300-8726-6	B3M549	Total/NA	Water	7196A	
MB 300-15899/3	Method Blank	Total/NA	Water	7196A	
LCS 300-15899/4	Lab Control Sample	Total/NA	Water	7196A	
300-8726-2 MS	B3LTK9	Total/NA	Water	7196A	
300-8726-2 DU	B3LTK9	Total/NA	Water	7196A	

Lab Chronicle

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Client Sample ID: B3LTK8**Date Collected: 11/15/18 09:00****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-1****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:32	TRH	TAL RCH

Client Sample ID: B3LTK9**Date Collected: 11/15/18 09:00****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-2****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:32	TRH	TAL RCH

Client Sample ID: B3LTK0**Date Collected: 11/15/18 12:02****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-3****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:32	TRH	TAL RCH

Client Sample ID: B3LTJ9**Date Collected: 11/15/18 12:02****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-4****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:33	TRH	TAL RCH

Client Sample ID: B3LTK5**Date Collected: 11/15/18 09:32****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-5****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:33	TRH	TAL RCH

Client Sample ID: B3M549**Date Collected: 11/15/18 09:32****Date Received: 11/15/18 14:30****Lab Sample ID: 300-8726-6****Matrix: Water**

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:33	TRH	TAL RCH

TestAmerica Richland

Lab Chronicle

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Client Sample ID: Method Blank

Lab Sample ID: MB 300-15899/3

Date Collected: N/A

Matrix: Water

Date Received: N/A

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:28	TRH	TAL RCH

Client Sample ID: Lab Control Sample

Lab Sample ID: LCS 300-15899/4

Date Collected: N/A

Matrix: Water

Date Received: N/A

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:29	TRH	TAL RCH

Client Sample ID: B3LTK9

Lab Sample ID: 300-8726-2 MS

Date Collected: 11/15/18 09:00

Matrix: Water

Date Received: 11/15/18 14:30

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:29	TRH	TAL RCH

Client Sample ID: B3LTK9

Lab Sample ID: 300-8726-2 DU

Date Collected: 11/15/18 09:00

Matrix: Water

Date Received: 11/15/18 14:30

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1			15899	11/15/18 16:32	TRH	TAL RCH

Laboratory References:

TAL RCH = TestAmerica Richland, 2800 George Washington Way, Richland, WA 99352, TEL (509)375-3131

Method Summary

Client: CH2M Hill Plateau Remediation Company
Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
SDG: RL8726-1

Method	Method Description	Protocol	Laboratory
7196A	Chromium, Hexavalent	SW846	TAL RCH

Protocol References:

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

TAL RCH = TestAmerica Richland, 2800 George Washington Way, Richland, WA 99352, TEL (509)375-3131



Sample Summary

Client: CH2M Hill Plateau Remediation Company
 Project/Site: I19-004

TestAmerica Job ID: 300-8726-1
 SDG: RL8726-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
300-8726-1	B3LTK8	Water	11/15/18 09:00	11/15/18 14:30
300-8726-2	B3LTK9	Water	11/15/18 09:00	11/15/18 14:30
300-8726-3	B3LTK0	Water	11/15/18 12:02	11/15/18 14:30
300-8726-4	B3LTJ9	Water	11/15/18 12:02	11/15/18 14:30
300-8726-5	B3LTK5	Water	11/15/18 09:32	11/15/18 14:30
300-8726-6	B3M549	Water	11/15/18 09:32	11/15/18 14:30

Login Sample Receipt Checklist

Client: CH2M Hill Plateau Remediation Company

Job Number: 300-8726-1

SDG Number: RL8726-1

Login Number: 8726**List Number: 1****Creator: Holm, Tina R****List Source: TestAmerica Richland**

Question	Answer	Comment
Radioactivity wasn't checked or is </= background as measured by a survey meter.	True	
The cooler's custody seal, if present, is intact.	N/A	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	N/A	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	N/A	
Multiphasic samples are not present.	N/A	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	