


Control Number: 117	300 NPL Agreement/Change Control Form <input type="checkbox"/> Change <input checked="" type="checkbox"/> Agreement <input type="checkbox"/> Information Operable Unit(s): 300-FF-1	Date Submitted: December 9, 1997 Date Approved: 12/17/97
Document Number/Title: 300-FF-1 Waste Site 300-44 Verification Package (BHI-01135)		Date Document Last Issued: N/A
Originator: Charlie Johnson		Phone: 373-6372
Summary Discussion: Remediation of waste site 300-44 was completed in accordance with the <i>300-FF-1 Remedial Design Report/Remedial Action Work Plan (RDR/RAWP)(DOE/RL-96-70)</i> . Contaminated soil was removed from the site and sent to the Environmental Restoration Disposal Facility (ERDF). Analysis of verification samples showed that remaining soil within the area is below the 300-FF-1 cleanup standards. Analysis of samples from the 300-44 overburden stockpile adjacent to the waste site showed that the material was acceptable for use as backfill material. The waste site no longer poses an unacceptable threat to human health or the environment as demonstrated in the referenced verification package.		
Justification and Impact of Change: This form documents agreement among the parties listed below to classify the subject waste site from the TPA solid waste management unit listing as closed out. Final removal from the NPL will occur at a future date.		
V.R. Dronen BHI Project Manager	 Date 12/17/97	
R.G. McLeod DOE Project Manager	Date 12-17-97	
N/A – EPA Lead Site Ecology Project Manager	Date	
D.R. Einan EPA Project Manager	Date 17 Dec 97	
Per Action Plan for Implementation of the Hanford Consent Order and Compliance Agreement Section 9.3		