Waste Site Reclassification Form

Date Submitted: 2/8/	Operable Unit(s)	<u>:</u> 200-PO-3	Control Number: 2001-025
Originator: S. G. Weis	Waste Site ID:	2607-EJ	
Phone: 372-9495	Type of Reclassi Rejecte Closed	d O	
	No Acti	on O	
This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.			
Description of current waste site condition: The 2607-EJ Septic System was the original system that serviced the 272-AW building. The tank and drainfield have been removed.			
		j	
	on: n was removed during site preparation for (50 foot) deep excavation for the tank		m. The tank and drainfield were in
HAROLD J. ST DOE Project Manager	//	rioli V. Stafford Ja.	2/22/01 Date
D ーソレマ Ecology Project Mana	ger Signa	Wien Sear	5-31-0 (Date
EPA Project Manager	- μ	ature	Date