

## Waste Site Reclassification Form

<b>Date Submitted:</b> 1/29/2001 <b>Originator:</b> J. M. Golden  <b>Phone:</b> 376-6961	<b>Operable Unit(s):</b> 100-IU-6 <b>Waste Site ID:</b> 600-240  <b>Type of Reclassification Action:</b> Rejected <input checked="" type="radio"/> Closed-Out <input type="radio"/> No Action <input type="radio"/>	<b>Control Number:</b> 2001-018
---	---	---------------------------------

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

The site is metal and wooden debris scattered within Gravel Pit #17. The debris originated from the 615 Hot Mix Plant and operation of the gravel pit (Hanford Aggregate Pit). Some of the pipes and wood are partially buried in scattered locations. The pile is naturally revegetating to grasses and rabbitbrush. To the east of the pit is an irregularly shaped pile of a mix of asphalt pieces, soil, gravel, and cobble, about 12 meters by 3.5 meters by 1 meter high (40 feet by 12 feet by 3 feet high). Rabbitbrush plants have started to colonize the pile.

**Basis for reclassification:**

There is no evidence of hazardous or dangerous materials at the site.

Steve Buerbaum	Steve Buerbaum	2/23/2001
DOE Project Manager	Signature	Date
NA		
Ecology Project Manager	Signature	Date
Craig E. Cameron	Craig E. Cameron	5/31/01
EPA Project Manager	Signature	Date