

1218134

0635318

105-N & 109-N SAFE STORAGE ENCLOSURE (SSE) FINAL
ROOM STATUS REPORT

SECTION 4 OF 11

PHOTO # 100/109N/Access Bldg. North Wall Above Grade/02-15-2012




PHOTO # 101/109N/Area Below SSE Roof-Access Door/EI.40'/02-07-2012



PHOTO # 102/109N/Area Under SSE Roof-Access Door/EI.40'/02-15-2012



PHOTO # 103/109N/Area Under SSE Roof-North Wall East End/EI.40'/02-07-2012



PHOTO # 104/109N/Area Under SSE Roof-East Vent Valve Struct. Looking East/EI.40'/02-07-2012



PHOTO # 105/109N/Area Under SSE Roof-East Wall Ctr./El.40'/El.40'/02-07-2012



PHOTO # 106/109N/Area Under SSE Roof-SW Corner/EI.40'/02-07-2012



PHOTO # 107/109N/Area Under SSE Roof-South Wall E.End/EI.40'/02-07-2012



PHOTO # 108/109N/Area Under SSE Roof-North Wall E. of Press./El.40'/02-07-2012



PHOTO # 109/109N/Area Under SSE Roof-E.Wall of Press./El.40'/02-07-2012



PHOTO # 110/109N/Area Under SSE Roof-West ½ Roof/EI.40'/02-07-2012



PHOTO # 111/109N/Area Under SSE Roof-W.Side of Press./El.40'/02-07-2012



PHOTO # 112/109N/Area Under SSE Roof-N.Wall W.of Press./El.40'/02-07-2012




PHOTO # 113/109N/Area Under SSE Roof-Ctr.Vent Valve Struct./El.40'/02-07-2012



PHOTO # 114/109N/Area Under SSE Roof-W.Vent Valve Struct./El.40'/02-07-2012



PHOTO # 115/109N/Area Under SSE Roof-West Wall/EI.40'/02-07-2012



PHOTO # 116/109N/Area Under SSE Roof-S.Wall W.End/EI.40'/02-07-2012



PHOTO # 117/109N/Area Under SSE Roof-South Wall Ctr./El.40'/02-07-2012



PHOTO # 118/109N/SSE Roof-Tie-In to S.Side 105N/09-21-2011



PHOTO # 119/109N/SSE Roof- Tie-In to S.Side 105N & Press./09-21-2011




PHOTO # 120/109N/SSE Roof-Expansion Jt. Cover At Press./09-21-2011



PHOTO # 121/109N Pressurizer/SSE Roof NW Corner/04-06-2011



PHOTO # 122/109N Pressurizer/SSE Roof-SW Corner/04-06-2011




PHOTO # 123/109N Pressurizer/SSE Roof-East Side/04-06-2011



PHOTO # 124/109N Pressurizer/SSE Roof-Bent Pl.Closure/04-06-2011



PHOTO # 125/109N Pressurizer/SSE Roof-Sealed Penetr./04-06-2011



PHOTO # 126/109N Pressurizer/SSE Roof-Cover Plate/04-06-2011



PHOTO # 127/109N Pressurizer/SSE Roof North Side/04-06-2011



PHOTO # 128/109N Pressurizer/SSE Roof-NW Corner/04-06-2011



PHOTO # 129/109N Pressurizer/SSE Roof-West Side/04-06-2011



PHOTO # 130/109N Pressurizer/SSE Roof-SE Corner/04-06-2011



PHOTO # 131/109N Pressurizer/SSE Roof-SE Corner/04-06-2011



PHOTO # 132/109N Pressurizer/SSE Roof-South Side/04-06-2011



PHOTO # 133/109N Pressurizer/SSE Roof-SW Corner/04-06-2011



PHOTO # 134/109N Pressurizer/SSE Roof Looking NW/04-06-2011



PHOTO # 135/109N Pressurizer/SSE Roof Looking North/04-06-2011



PHOTO # 136/109N Pressurizer/Top of Roof/04-06-2011



PHOTO # 137/109N Pressurizer/SSE-Roof East Side/04-20-2011



PHOTO # 138/109N Pressurizer/SSE Roof-North Side/04-20-2011



PHOTO # 139/109N Pressurizer/SSE Roof-West Side/04-20-2011




PHOTO # 140/109N Pressurizer/SSE Roof-South Side/04-20-2011




PHOTO # 141/109N Pressurizer/SSE Roof-South Side Downspout/04-20-2011




PHOTO # 142/109N Pressurizer/SSE Roof-NW Side/08-18-2011



PHOTO # 143/109N W.Wall N.End Pourbacks/El.Varies/06-26-2012



PHOTO # 144/109N W.Wall Below Grade Looking North/EI.Varies/07-10-2012



PHOTO # 145/109N W.Wall Below Grade Pourback (10" BD Line)/El.Varies/07-10-2012



PHOTO # 146/109N W.Wall Below Grade Looking South/EI.Varies/07-10-2012



PHOTO # 147/109N W.Wall Below Grade S.End/EI.Varies/07-10-2012



PHOTO # 148/109N W.Wall Below Grade SW Corner/EI.Varies/07-10-2012

