

1218134

0635318

105-N & 109-N SAFE STORAGE ENCLOSURE (SSE) FINAL
ROOM STATUS REPORT

SECTION 11 OF 11

PHOTO # 504/105N/Rod Rm. SSE Roof-Looking South/El.Varies/08-18-2011



PHOTO # 505/105N/Rod Rm. SSE Roof-Flashing at NE Corner/EI.Varies/08-18-2011



PHOTO # 506/105N/Rod Rm. SSE Roof-Gutter at Main Roof W. Side/EI.Varies/08-18-2011



PHOTO # 507/105N/Rod Rm. SSE Roof-Gutter at Main Roof W. Side/EI.Varies/08-18-2011



PHOTO # 508/105N/Main & Rod Rm. SSE Roof/EI.Varies/03-12-2012



PHOTO # 509/105N/Rm.#507 East End at Top of Stair#8/El.+43'-6"/06-05-2012




PHOTO # 510/105N/Rm.#507 Looking East/EI.+43'-6"/06-05-2012



PHOTO # 511/105N/Rm.#507 Looking West/EI.+43'-6"/06-05-2012



PHOTO # 512/105N/Rm.#507 Ceiling Looking West/EI.+43'-6"/06-05-2012



PHOTO # 513/105N/Rm.#175 View Window & Platform-Looking NW/EI.+33'-9"/06-05-2012




PHOTO # 514/105N/Rm.#175 View Window & Platform-Looking NE/EI.33'-9"/06-05-2012



PHOTO # 515/105N/Stair#8 Looking Down from Platform/EI.+33-9"/06-05-2012



PHOTO # 516/105N/Rm.#175 Intermediate Equip.-Looking North/EI.+15'-0"/06-05-2012




PHOTO # 517/105N/Rm.#175 North Wall/EI.Varies/06-05-2012



PHOTO # 518/105N/Stair#8-Looking East/EI.+1'-0"/06-05-2012



PHOTO # 519/105N/Rm.#175-Looking East/EI.+1'-0"/06-05-2012



PHOTO # 520/105N/Rm.#175-Looking West/EI.+1-0"/06-05-2012



PHOTO # 521/105N/Rm.#175-Discharge Tunnel Cover Plates/El.+1-0"/06-05-2012



PHOTO # 522/105N/Corridor#7 East End Cover Plate/EI.+5'-0"/06-05-2012



PHOTO # 523/105N/Corridor#7East End Looking West/EI.+5'-0"/06-05-2012



PHOTO # 524/105N/Corridor#7 Center Looking West/EL.+5'-0"/06-05-2012



PHOTO # 525/105N/Corridor#7 Center Looking West/EI.+5'-0"/06-05-2012



PHOTO # 526/105N/Corridor#7 Center Looking East/EI.+5'-0"/06-05-2012



PHOTO # 527/105N/Corridor#7 West End Looking West/EI.+5'-0"/06-05-2012



PHOTO # 528/105N/Corridor#7 Ceiling West End/El.+5'-0"/06-05-2012



PHOTO # 529/105N/Corridor#7 West End Looking East/EI.+5'-0"/06-05-2012



PHOTO # 530/105N/Corridor#7 FW Pipe at West End/EI.+5'-0"/06-05-2012



PHOTO # 531/105N/Corridor#7 West End Looking East/EI.+5'-0"/06-05-2012



PHOTO # 532/105N/Corridor #22 Shld Door at East Wall/EI.0'-0"/07-17-2012



PHOTO # 533/105N/Corridor #22 Looking North/EI.0'-0"/07-17-2012




PHOTO # 534/105N/Corridor#22 Looking North/EI.0'-0"/07-17-2012



PHOTO # 535/105N/Corridor #22 Looking NE/EI.0'-0"/07-17-2012



PHOTO # 536/105N/Corridor #22 Looking South/EI.0'-0"/07-17-2012



PHOTO # 537/105N/Corridor #22 Looking SE/EI.0'-0"/07-17-2012



PHOTO # 538/105N/Corridor #22 Looking SW/EI.0'-0"/07-17-2012



PHOTO # 539/105N/Corridor #22 Floor Looking South/EI.0'-0"/07-17-2012



PHOTO # 540/105N/Corridor #22 N. Wall Exterior & N. Side Rod Rm./El.Varies/07-19-2012



PHOTO # 541/105N/Corridor #22 W. Exterior Wall & W. Wall of Rod Rm./El.Varies/07-19-2012



PHOTO # 542/105N/West Wall Below Grade-N. of Rod Rm./El.Varies/07-19-2012



PHOTO # 543/105N/West Wall Above Grade-N. of Rod Rm./El.Varies/07-19-2012



PHOTO # 544/105N/W. Wall Below Grade Between Rod Rm. & 109N/EI.Varies/07-19-2012



PHOTO # 545/105N/W.Wall Above Grade Between Rod Rm. & 109N/EI.Varies/07-19-2012



3.9 INDEX OF ALL CD DISC's FOR DIGITAL PHOTOS ASSOCIATED WITH 105-N & 109-N INSPECTIONS

105-N & 109-N SSE CD Digital Photos

INDEX

<u>CD No.</u>	<u>Bldg.No.</u>	<u>Photo Numbers</u>	<u>Description</u>
1	109N	---	Index of Photos- 109N
1	109N	#1 to #148	Digital Photos- 109N
2	105N	---	Index of Photos- 105N
2	105N	#201 to #348	Digital Photos- 105N
3	105N	#349 to #477	Digital Photos- 105N
4	105N	#478 to #545	Digital Photos- 105N

3.10 INDEX OF ALL DVD DISC's FOR VIDEO RECORDINGS ASSOCIATED
WITH 105-N & 109-N INSPECTIONS

105-N & 109-N SSE DVD Video Recordings

INDEX

DVD Disc No.	DVD Title No.	Date	Bldg.	Room No.	Elev.	Description/Location
1	01	05/04/11	109N	104	0'-0"	Water Quality Lab
1	02	05/04/11	109N	103	0'-0"	Water Quality Lab
1	03	05/04/11	109N	105	0'-0"	Water Quality Lab
1	03	05/04/11	109N	106	0'-0"	Water Quality Lab
2	01	09/01/10	109N	307	25'-1/2"	Sampling Rm.
2	02	09/01/10	109N	208	12'-8 1/2"	Sampling/Chem.Lab
2	03	09/01/10	109N	Str#7	0' to 25'-1/2"	Stair #7
3	01	02/14/12	109N	Access	0' to (-)16'-0"	109N Access Building
3	02	02/14/12	109N	Roof	Varies	109N Main Roof
4	01	04/06/11	109N	Roof	Varies	109N Pressurizer Roof
5	01	04/14/10	105N	4	(-)16'-0"	Ball Control Rm.
5	02	04/14/10	105N	5	(-)16'-0"	Left Rupture Monitor Rm.
5	03	04/14/10	105N	Cor.#3	(-)16'-0"	Corridor #3
6	01	02/23/12	105N	172, 173, 174	5'-0"	Access/Tool Rm.
6	02	02/23/12	105N	7,8,9	(-)15'-0"	Mech./Elect. Rm.
6	03	02/23/12	105N	R Elev.	(-)24'-0"	R Elevator Pit
6	04	02/23/12	105N	302, 301	16'-6"	Access/Elect. Rm.
6	05	02/23/12	105N	402, 401	28'-3"	Access/Equip. Rm.
6	06	02/23/12	105N	Str#6	(-)24' to 40'	Stair #6
6	07	02/23/12	105N	Str#6A	40' to 60'-6"	Stair #6A
7	01	02/14/12	105N	501, 502	40'-0"	Access/Elect. Rm.
7	02	02/14/12	105N	503	40'-0"	Access/Elect. Rm.
7	03	02/14/12	105N	520	51'-0"	Access/Elect. Rm.
7	04	02/14/12	105N	601 to 613	60'-6"	Equip. Rm.
8	01	08/25/11	105N	29	0'-6"	Front Face
9	01	10/27/10	105N	35,41	(-)21'-0"	Pipe Tunnel
9	02	10/25/10	105N	37	(-)10'-0"	Right Rupture Monitor Rm.
9	03	10/26/10	105N	Cor.#4	(-)8'-9"	Corridor #4
10	01	09/08/11	105N	Roof	Varies	105N Main Roof
10	02	08/01/11	105N	Roof	Varies	105N West Rod Rm. Roof

DVD Disc <u>No.</u>	DVD Title <u>No.</u>	<u>Date</u>	<u>Bldg.</u>	Room <u>No.</u>	<u>Elev.</u>	<u>Description/Location</u>
11	01	05/10/12	105N	11	(-)19'-0"	Fast Cart Tunnel

3.11 CD DIGITAL PHOTO INSPECTION DISC's

3.12 DVD VIDEO INSPECTION DISC's

ALL DVD'S ARE AVAILABLE IN THE
AR ROOM 1101 OF THE 2440 BLDG