

## Waste Site Reclassification Form

<b>Date Submitted:</b> 11/2/2004	<b>Operable Unit(s):</b> 200-RO-3	<b>Control Number:</b> 2004-117
<b>Originator:</b> CR Webb	<b>Waste Site ID:</b> 296-S-6	
<b>Phone:</b> 373-5573	<b>Type of Reclassification Action:</b>	
	<b>Rejected:</b> <input checked="" type="radio"/>	
	<b>No Action:</b> <input type="radio"/>	
	<b>Interim Closed Out:</b> <input type="radio"/>	
	<b>Closed Out:</b> <input type="radio"/>	




This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

The stack is located on the roof in the northeast corner of 202-S. 296-S-6 was built to discharge unfiltered air from the silo gallery, organic feed tank and sample elevator.

**Basis for reclassification:**

The stack is attached to the 202-S building. The site should be Rejected (Consolidated) with the 202-S WIDS site.

		
DOE Project Manager	Signature	Date
Ecology Project Manager	Signature	Date
		
EPA Project Manager	Signature	Date