

## Waste Site Reclassification Form

<b>Date Submitted:</b> 10/28/2004	<b>Operable Unit(s):</b> 200-RO-3	<b>Control Number:</b> 2004- 115
<b>Originator:</b> CR Webb	<b>Waste Site ID:</b> 296-S-4	
<b>Phone:</b> 10/28/2004	<b>Type of Reclassification Action:</b>	
	<b>Rejected:</b> <input checked="" type="radio"/>	
	<b>No Action:</b> <input type="radio"/>	
	<b>Interim Closed Out:</b> <input type="radio"/>	
	<b>Closed Out:</b> <input type="radio"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

The unit discharged filtered air from the decontamination room and regulated shop and unfiltered air from the regulated tool room low-level decontamination sink and Special Work Permit (SWP) lobby. The stack is located on the east outside wall of the 202-S building.

**Basis for reclassification:**

The stack is attached to the 202-S building. The site should be Rejected (Consolidated) with the 202-S WIDS site.

*F. M. Roddy*  
DOE Project Manager

Signature

*11/10/04*  
Date

Ecology Project Manager

Signature

Date

*Craig Cameron*  
EPA Project Manager

Signature

*11/10/04*  
Date