

1250355
[00645167]



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

3100 Port of Benton Blvd • Richland, WA 99354 • (509) 372-7950
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

October 19, 2018

18-NWP-170

By certified mail

Doug S. Shoop, Manager
Richland Operations Office
United States Department of Energy
PO Box 550, MSIN: H5-20
Richland, Washington 99352

Ty Blackford, President and CEO
CH2M HILL Plateau Remediation Company
PO Box 1600, MSIN: A7-01
Richland, Washington 99352

Re: Department of Ecology (Ecology) Review of Response to Dangerous Waste Compliance Inspection on June 5, 2018, at 1301-N Liquid Waste Disposal Facility, 1325-N Liquid Waste Disposal Facility, 183-H Solar Evaporator Basins, and 300 Area Process Trenches, RCRA Site ID: WA7890008967, NWP Compliance Index No's 18.634 through 18.637.

Reference: See page 2

Dear Doug S. Shoop and Ty. Blackford:

Ecology has reviewed your response letter and enclosure, received on October 16, 2018 (reference). Your letter included corrective action for an item of non-compliance identified in Ecology's June 5, 2018, inspection of the 183-H Solar Evaporator Basins. As of October 16, 2018, area of non-compliance one has been addressed.


As described in your letter, on May 24, 2017, the groundwater monitoring plan for 183-H was incorporated into the *Hanford Facility Resource Conservation and Recovery Act Permit, Dangerous Waste Portion, Revision 8C* (the Permit). Therefore, Ecology expectations are, and in accordance with the Permit, that Wells 199-H4-88 and 199-H4-89 continue to be sampled quarterly for two years from the first time that quarterly monitoring began.

Ecology may re-inspect your facility to verify that these steps were completed, and that your facility remains in compliance.

If you have questions or need further information, please contact me at jared.mathey@ecy.wa.gov or (509) 372-7949.

Sincerely,

Jared Mathey
Dangerous Waste Compliance Inspector
Nuclear Waste Program



am
cc: See page 2



1250336

Doug S. Shoop and Ty Blackford
October 19, 2018
Page 2 of 2

18-NWP-170
1301-N, 1325-N, 183-H, and 300 APT
RCRA Site ID: WA7890008967
NWP Compliance Index No.: 18.634 through 18.637
Inspection Date: June 5, 2018

Reference:

1250336

1. Letter 18-ESQ-0105, received on October 16, 2018, "Response to dangerous waste compliance inspection on June 5, 2018, at the 1301-N Liquid Waste Disposal Facility, 1325-N Liquid Waste Disposal Facility, 183-H Solar Evaporator Basins, and 300 Area Process Trenches, Resource Conservation and Recovery Act (RCRA) Site ID: WA7890008967, Nuclear Waste Program Compliance Index Nos.: 18.634 through 18.637"

cc electronic:

Dave Bartus, EPA
 Jack Boller, EPA
 Dave Einan, EPA
 Duane Carter, USDOE
 Cliff Clark, USDOE
 Michael Cline, USDOE
 Doug Hildebrand, USDOE
 Tony McKarns, USDOE
 Allison Wright, USDOE
 Randall Fox, CHPRC
 Linda Petersen, CHPRC
 Jon Perry, MSA
 ERWM Staff, YN
 Ken Niles, ODOE
 Debra Alexander, Ecology
 Kathy Conaway, Ecology

Suzanne Dahl, Ecology
 Dib Goswami, Ecology
 Brian Johnson, Ecology
 Stuart Luttrell, Ecology
 Jared Mathey, Ecology
 Nina Menard, Ecology
 John Price, Ecology
 Stephanie Schleif, Ecology
 Ron Skinnarland, Ecology
 Alex Smith, Ecology
 Cheryl Whalen, Ecology
 Environmental Portal
 Hanford Facility Operating Record
 CHPRC Correspondence Control
 MSA Correspondence Control
 USDOE-RL Correspondence Control

cc:

Susan Leckband, HAB
Administrative Record
 NWP Central File
 NWP Compliance Index File: 18.634 through 18.637
 Matt Johnson, CTUIR
 Jack Bell, NPT
 Rose Longoria, YN

