Waste Site Reclassification Form

Date Submitted: 2/13/2001	**Operable Unit(s):** 200-ST-1	**Control Number:** 2001-028
Originator: S. G. Weiss	**Waste Site ID:** 600 NSTFST	
Phone: 372-9495	**Type of Reclassification Action:**	
	Rejected ○	
	Closed-Out ◉	
	No Action ○	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

This site is a septic tank and associated tile field. This site is located at the west end of Gable Mountain, at the base of the north side. The septic tank serviced the Trailer Village for the Near Surface Test Facility.

Basis for reclassification:

Decommissioning and reclamation activities at the Near Surface Test Facility were completed March 23, 1988. The septic tank was pumped out and backfilled.

Thomas Ferns	Thomas Ferns	3/21/01
DOE Project Manager	Signature	Date
Wayne Soper	Wayne Soper	5-31-01
Ecology Project Manager	Signature	Date
NA		
EPA Project Manager	Signature	Date